



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23005763/Rnp3e2 Date: 23/06/2023 Code: LIP	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLJ 5426C	Veh. Inspected	SJL 3451E	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS23/1781	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	06/06/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA ALLION 1.5A	c.c	1496	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	NZT2603034272	Colour	WHITE	
Odometer	195876 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/45 R17	MICHELIN	6 mm	
L/H Front Tyre	225/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	225/45 R17	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	30/05/2023	Inspection Date	07/06/2023	
Survey held at	OME MOTOR 50 BUKIT BATOK STREET 23 #01-12 MIDVIEW BUILDING SINGAPORE 659578			
<b>5a. Remarks</b>				
A)REGISTRATION DATE: 24 NOV 2008 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	