



LION CITY RENTALS PTE LTD
4 Jalan Besut S(619557)

Lonpac Insurance Bhd

Date : 07-Jun-23

Attn : MOTOR CLAIMS DEPT

VEHICLE NO. : SLQ9763R
CHASSIS NO : JTDKB3FUX03562369
MAKE / MODEL : Prius Hybrid
DATE OF ACCIDENT: 06-Jun-23
YOUR INSURED VEHICLE NUMBER : GBE5732M

	<u>PARTS DISCRIPTION</u>		<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	REAR BOOT <i>bl</i>		1PC	\$ 1,247.20	\$ 1,247.20
2	REAR WINDSCREEN GLASS MOULDING <i>ae</i>		1PC	\$ 250.00	\$ 250.00
3	REAR BOOT OUTER GARNISH <i>scr</i>		1PC	\$ 380.00	\$ 380.00
4	REAR BOOT HYBRID EMBLEM <i>ae</i>		1PC	\$ 89.00	\$ 89.00
5	REAR BOOT PRIUS EMBLEM <i>ae</i>		1PC	\$ 89.00	\$ 89.00
6	REAR BOOT TOYOTA LOGO <i>ae</i>		1PC	\$ 110.00	\$ 110.00
7	REAR BUMPER <i>ca</i>		1PC	\$ 487.60	\$ 487.60
8	REAR BUMPER LOWER <i>scr</i>		1PC	\$ 456.00	\$ 456.00
9	REAR BUMPER EXTENSION FILLER <i>X</i>	LH RH	1PC	\$ 80.00	\$ 80.00
10	REAR BUMPER RETAINER <i>X</i>	LH RH	1PC	\$ 60.00	\$ 60.00
11	REAR BUMPER REINFORCEMENT <i>st</i>		1PC	\$ 376.30	\$ 376.30
12	REAR END PANEL <i>st</i>		1PC	\$ 655.30	\$ 655.30
13	REAR END PANEL TOP GARNISH <i>?</i>		1PC	\$ 210.00	\$ 210.00
14	REAR BUMPER TOW COVER <i>X</i>		1PC	\$ 65.00	\$ 65.00
15	REAR TAILLAMP LOWER <i>X</i>	LH RH	1PC	\$ 525.00	\$ 525.00
16	REAR TAILLAMP UPPER <i>X</i>	LH RH	1PC	\$ 456.50	\$ 456.50
Total					\$ 5,536.90
Less 25%					\$ 1,384.23
Total					\$ 4,152.68

	<u>SPECIAL NETTS</u>		<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	REVERSE SENSORS <i>ae</i>		1	\$ 380.00	\$ 380.00 <i>200</i>
2	REAR TAILLAMP CLIPS <i>X</i>	LH RH	2	\$ 40.00	\$ 80.00 <i>X</i>
3	REAR BUMPER CLIPS <i>ae</i>		1	\$ 40.00	\$ 40.00 <i>✓</i>
4	REAR WINDSCREEN SEALANT <i>ae</i>		2	\$ 120.00	\$ 240.00 <i>60</i>
Total					\$ 620.00

LABOUR CHARGES

1	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.	\$ 800	1,600.00
2	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	\$ 900	1,200.00
3	TO CHECK REAR WIRES, CONNECTORS, REPLACE DAMAGED LAMPS REVERSE SENSOR	\$ 30	180.00
4	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	\$ 60	180.00
5	TO REMOVE AND INSTALL HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENTS FOR SAFETY PRECAUTIONS.	\$ X	380.00
6	REMOVE & REFIT REAR WINDSCREEN GLASS X 2	\$ 180	360.00
TOTAL		\$	3,900.00
TOTAL PARTS		\$	4,772.68
GRAND TOTAL		\$	8,672.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Panel
Hf 90010068
8 days
48
08/06/23 @ 1550
Revy after repair