/NC NS/INC23005806/Tnp3

ASSIGNMENT From: SHIA4226P Yr Regn: 20221 April. Date: Veh No: Estimated Cost: Type: M.Car / M.Cycle / Bus / Van / Lorry / Tax / Prime Mover / OD / TP) WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or To Inspect Vehicle No: Make: at Workshop m/s Colour Insured / Std / NI / NA Sp.Reading T/Radio: Insured / Std / NI / NA Insured: Eng/No: Policy No. C/No: Claims No. Gen. Cond: Good / Fair / Poor / Burnt Sum Insured: Excess: Steering: Inorder Jammed / Leaked / Burnt or (Client's Record) Brake: Inorder / Jammed / Leaked / Burnt or Make of Veh; Modi: (Nit / S/Rim / STD A/Rim or Tyre Size: (Policy Condition) Remark: The veh had commenced its N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / repair at the time of inspection. TOYO / YOKO or worthand Bal. or Market Value: Front IDAC Accident Roort Consistent? : Yes or No R/Bal. mm mm Consistent?: Yes or No GIA / PR Seen: L/Bal. UBal. mm 2 Est. Repairs: Res.: Yes or No days D.O.A. D.O.I. Lum Sum: 3 Val.: Yes or No Survey held at WY Des. of Damages : Frt / Rear / O/S Y N/S / U/C Y Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT Keer Person Contacted: Chian The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction Taufikh confirmed final fig \$1137.72 and 2 repair days (red, \$1196.85, 51%) Date/Time, File Pass to? : Preli. Report Days Of Repair: 2 : Final Report Resurvey No. of Trip: Survey Fee: Date/Time, File Return to? Transportation: Add Fee: :Site Insp (\$ S+RS__SI : Interview (\$ Pholos Representat: : Tech. Invs (\$ Others Lump Sum/LEA: (% Weellend (\$ TOTAL

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO

SHA4226P

01.06.2023

MAKE/REG

29.04.2022

CHIANG/INCOME

MODEL	TOYOTA	PRIUS G4

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER CLIPS		
1	REAR BUMPER	,R	> \$551.89
1	REAR BUMPER RETAINER RH	7/1	× \$112.70
10	REAR BUMPER CLIPS	\$2.20	\$ \$22.00
1	REAR BUMPER LOWER COVER	a a	\$654.96
1	REAR BUMPER REFLECTOR RH	n^	× \$55.00
	SUB TOTAL		\$1,396.5
	25.00%		\$349.13
	DISCOUNTED TOTAL		\$1,047.44
	REAR REVERESE SENSOR REAR BUMPER MAT	W.V.	× \$135.70 × \$50.00
	Labour Charge Panel Beating Spray Painting Charge Tuff Kote Remove and Refix Reverse Sensor TOTAL LABOUR	N.V.	\$167.13 \$700.00 \$300.00 \$60.00 \$1,120.00
	ESTIMATE TOTAL		\$2,334.5
	A		
	be prepared after the vehicle is surveyed by a motor Surveyor a	ppointed by the insurance comp	any.

Tangthe 97495749 "WP 76/13 @ 330 pm O 2 days tengthis of Whento. com P/P Resurvey new part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 07.06.2023 13:11 Page:

Team: ARC Repair TP(CLSO) Sales Order: 5899388

3055569

305556909 SHA4226P

COMFORT TRANSPORTATION PTE LTD

7010045

383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

TOYOTA

PRIUS HYBRID (G4A 07.06.2023 10

29.04.2022

JTDKB3FU503096415

Accident Date: 01.06.2023 NATURE: 3P 01.06.2023

S/NO LABOR CODE DESCRIPTION

SHA4226P CHIANG

SHA4226P