NS/INC23005807/Tqp3

ASSIGNMENT From: SHBZZ85B YrRegn: 24.6, Dec. Date: Veh No: Estimated Cost: Type: M.Car / M.Cycle / Bus / Van / Lorry / Tax / / Prime Mover / OD / TP / WS / TP RES / OD RES / EVA / INV / MV Truck / Traller or To Inspect Vehicle No: Make: at Workshop m/s Colour Insured / Std / NI / NA Sp.Reading T/Radio: Insured / Std / NI / NA Insured: Eng/No: Policy No. C/No: Claims No. Gen. Cond: Good/Fair/Poor/Burnt Sum Insured: Steering: Inorder/ Jammed / Leaked / Burnt or (Client's Record) Brake: Inorder / Jammed / Leaked / Burnt or Make of Veh: Modi: NIT / S/Rim / STD A/Rim or Tyre Size: (Policy Condition) Remark: The veh had commenced its N/S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / repair at the time of inspection. TOYO / YOKO or Westake. Bal. or Market Value: Front Rear IDAC Accident Roort Consistent? : Yes or No R/Bal. R/Bal. mm Consistent?: Yes or No GIA / PR Seen: L/Bal. mm Est. Repairs: days Res.: Yes or No D.O.A. D.O.I. Lum Sum: 3 Val.: Yes or No Survey held at Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time | Action / Instruction Taufikh finalised LS \$2950, 2 days. (Red \$3942.20, 57%) Date/Time, File Pass to? : Preli. Report Days Of Repair: 2 19/06 Typist : Final Report Resurvey No. of Trip: Survey Fee: Date/Time, File Return to? Transportation: Add Fee: :Site Insp (\$ _S + RS__SI : Interview (\$ Pholos Representat: TP : Tech. Invs (\$ Others Lump @ 45 4 2950 Weellend (\$

TOTAL

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHB2285B

Date: 07/06/2023

Make

: HYUNDAI

Insurance: INCOME

Model : 1-40 MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
1	FRT BUMPER COVER			\$ 1,052.20
10	FRT BUMPER CLIPS			\$ 22.00
1	RADIATOR GRILLE			\$ 1,480.00
1	HEADLAMP RH			\$ 1,388.00
1	FRT BUMPER REINFORCEMENT			\$ 588.40
1	FRT BUMPER TOP BRACKET RH			\$ 44.80
1	FRT BUMPER SIDE BRACKET RH			\$ 24.60
1	HEADLAMP SUPPORT PANEL ASSY			\$ 907.40
1	FRT BUMPER GRILLE RH			\$ 126.20
1	FRT FENDER SHIELD RH			\$ 174.90
1	FRT FENDER RH			\$ 663.00
	SUB TOTAL			\$ 6,471.50
	LESS 20%	1		\$ 1,294.30
	DISCOUNTED TOTAL			\$ 5,177.20
	FRT NUMBER PLATE WITH TRIM COVER			\$ 55.00
	RENEW ADVERTISEMENT STICKER			\$ 100.00
			NETT	\$ 155.00
	Labour Charge			
	CHL ALL LIGHTING			\$ 60.00
	PANEL BEATING		A	\$ 900.00
	SPRAY PAINTING CHARGE			\$ 600.00
	TOTAL LABOUR			\$ 1,560.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 1



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Mainline + 65 6383 6280 Facsimile + 65 6280 9
Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 575717

45 Pandan Road Singapore 609286
45 Pandan Road Singapore 575717

Page : 1

ARC Repair TP(CFSO)1 eam:

JOB CARD Sales Order: 5899372

JC NO305556904

TOMER	REGN NO.: SHB2285B	MILEAGE	
MS CITYCAB PTE LTD 7010070	MAKE HYUNDAI	FUEL EF	
TOMER NO. 7010070 RESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65551188 (O)	MODEL 1-40 06	.06.2023 16:40	
	YR OF MANU. 08.12.2016	TARGET DATE	
COUNT CARD NO.	CHASSIS CODE KMHLB41UMHU097203	COMPLETION DATE/TIME:	


JOB DESCRIPTION

ccident Date: 06.06.2023 ATURE: 3P 06.06.2023 '

/NO

LABOR CODE

DESCRIPTION



			5		
CKED & PASSED OUT BY:					
SERVICE ADVISOR	-	CUSTOMER'S SIGNATURE			
rledgement Slip	Exit Pass				
No.: SHB2285B YY	Vehicle No.: SHB2285B				
Signature/Date sturned to Service Reception upon collection	Name of Service Advisor To be kept by Security Guard	Date			