

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHB2285B

Make : HYUNDAI

Model : I-40

Date: 07/06/2023

Insurance: INCOME

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$ 1,052.20
10	FRT BUMPER CLIPS			\$ 22.00
1	RADIATOR GRILLE			\$ 1,480.00
1	HEADLAMP RH			\$ 1,388.00
1	FRT BUMPER REINFORCEMENT			\$ 588.40
1	FRT BUMPER TOP BRACKET RH			\$ 44.80
1	FRT BUMPER SIDE BRACKET RH			\$ 24.60
1	HEADLAMP SUPPORT PANEL ASSY			\$ 907.40
1	FRT BUMPER GRILLE RH			\$ 126.20
1	FRT FENDER SHIELD RH			\$ 174.90
1	FRT FENDER RH			\$ 663.00
			3324.70	
			2659.76	
	SUB TOTAL			\$ 6,471.50
	LESS 20%			\$ 1,294.30
	DISCOUNTED TOTAL			\$ 5,177.20
	FRT NUMBER PLATE WITH TRIM COVER		100	\$ 55.00
	RENEW ADVERTISEMENT STICKER			\$ 100.00
			NETT	\$ 155.00
	Labour Charge		950	\$ 60.00
	CHL ALL LIGHTING			\$ 900.00
	PANEL BEATING			\$ 600.00
	SPRAY PAINTING CHARGE			\$ 1,560.00
	TOTAL LABOUR		3709.76	
			4542950	
			02day	
	ESTIMATE TOTAL			\$ 6,892.20

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: