



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: SLA2078R

Date: 13 JULY 2023

Our Ref: CC2/CNB23005809/Dp

M/s CENTRAL NARCOTICS BUREAU
CORPORATE SERVICES DIVISION
BLK B
POLICE CANTONMENT COMPLEX
393 NEW BRIDGE ROAD
(S) 088763

Attn: Mr Mohamad Juahir (Logistics Unit)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO. SLK5628G
CNB VEHICLE NO. SLA2078R
DATE OF ACCIDENT: 10 MAY 2023

We thank you for your instruction on 24 MAY 2023.

We acknowledge receipt of the following documents: -

- a) Police report of Vehicle SLA2078R.
- b) Damaged vehicle photographs of SLK5628G.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments: -

1. Information Recorded: -
 - Registration Number : SLK5628G
 - Make & Model : Honda Civic
 - Engine Capacity : 1500 cc



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

2. Our finding is that the repair cost of 350.00 (before GST) quoted by M/s Astee Autolution Pte Ltd is fair & reasonable. The repair cost includes repair and spray paint for the damage of front left fender and front bumper.

3. We recommend that the repairs of the damage require about 1 (One) working day to complete.

Yours faithfully

ANG BRYAN TANI
Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.