



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3939Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	481.10	-
1	FRONT DOOR HANDLE RH	TO REPAIR SEE LABOUR	234.80	-
1	FRONT NUMBER PLATE W/HOLDER	CRACKED	55.00	55.00
1	REAR DOOR PANEL RH	BENT	1,789.90	1,789.90
	LESS 20% DISCOUNT		-512.16	-368.98
			2,048.64	1,475.92
<b>SPECIAL NETT ITEMS</b>				
1	REAR DOOR COMFORT APP STICKER (SN)	NECESSARY	80.00	80.00
1	REAR DOOR ADVERTISEMENT (SN)	NECESSARY	100.00	100.00
1	FRT DOOR COMFORT LOGO STICKER (SN)	NECESSARY	75.00	75.00
1	FRT DOOR ADVERTISEMENT RH (SN)	NECESSARY	100.00	100.00
			355.00	355.00
<b>LABOUR</b>				
	OD/TP CASE (INSURER).		11.00	11.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT DOOR HANDLE RH.		875.00	525.00
	SPRAY PAINTING.		800.00	750.00
	TRANSFER DOOR PARTS.		60.00	60.00
	TOWING FEE.		60.00	60.00
			1,806.00	1,406.00
<b>GRAND TOTAL</b>			<b>4,209.64</b>	<b>3,236.92</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>2,600.00</b>

Report Ref No. NS/INC23005810/Tvy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.