



Boxfresh Pte Ltd

7030 Ang Mo Kio Ave 5 #06-49
Northstar @AMK Singapore 569880
Tel : 64585441 Fax : 64553470

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Vehicle No : SBS6543L

Accident date : 4th Jun 2023

Model No : Mercedes

Registered owner : Go Ahead Singapore Pte Ltd

Citaro

Date of Estimate : 08/06/23

My Ref : BF-IC-1145

Total Charge

Parts Replaced (4 days)

- | | |
|---|-------------------------|
| 1) Replace Front windscreen P/N: 628 671 2210 | S\$3414.50 <i>one ✓</i> |
| 2) Replace NS Corner bumper P/N: 628 880 0172 | S\$1594.30 <i>one ✓</i> |
| 3) Replace NS lamp blinker P/N: 001 820 9121 | S\$130.80 <i>one ✓</i> |
| 4) Replace NS Headlamp P/N: 002 820 5061 | S\$1100.40 <i>one ✓</i> |
| 5) Replace WIPER PANEL P/N: 628687040700 | S\$765.60 <i>one ✓</i> |

Subtotal : S\$ 7005.60
10% - 6305.04

Parts Repair

- | | |
|---|------------------------|
| 1) Repair NS Front Side Cover | S\$80 ✓ |
| 2) Removal and installation of damage parts. | S\$1100 <i>800</i> |
| 3) Bostik Simson ISR70-05 Adhesive 6 tubes | S\$ 216 ✓ |
| 4) Bostik Simson primer G Plus(ADS-9000GP) 0.5 bottle | S\$45 ✓ |
| 5) Painting of all affected parts | S\$800 <i>600 1741</i> |

\$9246.60

Subtotal : S\$ 2241
*6305.04
(1741)
\$8046.04*

BOXFRESH PTE LTD

WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611

OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880

T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg

24 days #