

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

28, Gul Drive, Singapore 629476 Tel : 63531131

(Email Adress : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

OD CLAIM

To : Lonpac Insurance Bhd
Motor Claims Dept

Date : 07 Jun 2023

Dear Sirs :

Fax : 6896 8706

RE : ESTIMATE COST FOR MITSUBISHI FEB71 - YN9951B ALONG TEBAN GARDENS ON 15/05/2023

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front headlamp rh <i>br</i>	1pc	\$ 330.00
4	Front side lamp rh <i>br</i>	1pc	\$ 190.00
5	Front signal lamp rh <i>br</i>	1pc	\$ 158.00
6	Front bumper <i>bt</i>	1pc	\$ 520.00
7	Front bumper bracket @\$140ea <i>bt</i>	2pcs	\$ 280.00
8	Front bumper side rh <i>ca</i>	1pc	\$ 210.00
10	Front chassis crossmember <i>bt</i>	1pc	\$ 400.00
11	Front step panel rh <i>ca</i>	1pc	\$ 270.00
12	Front step garnish rh <i>ca</i>	1pc	\$ 220.00
13	Front pillar rh <i>bt</i>	1pc	\$ 900.00
14	Front door rh <i>br</i>	1pc	\$ 1,300.00
15	Front door rubber rh <i>ca</i>	1pc	\$ 220.00
16	Front door inner trim rh <i>de</i>	1pc	\$ 620.00
17	Front door lower garnish <i>de</i>	1pc	\$ 150.00
18	Front door hinge rh @\$110ea <i>bt</i>	2pcs	\$ 220.00
19	Front dashboard <i>de</i>	1pc	\$ 1,550.00
20	Front dashboard lower cover <i>ca</i>	1pc	\$ 310.00
21	Front dashboard end cover rh <i>ca</i>	1pc	\$ 150.00
22	Air con blower ?	1pc	\$ 550.00
	Sum Carried Forward		\$ 8,548.00

Sum Carried Forward

\$ 8,548.00

23	Air con heater ?	1pc	\$	1,450.00
24	Front step wheel garnish <i>ca</i> /	1pc	\$	210.00
25	Front door glass rh <i>bu</i> /	1pc	\$	300.00
26	Front door reguator rh ?	1pc	\$	500.00
27	Front pillar inner garnish rh ?	1pc	\$	250.00
28	Front windscreen glass <i>bu</i> /	1pc	\$	500.00
29	Front windscteen rubber <i>bu</i> /	1pc	\$	150.00
30	Front wiper panel <i>de</i> /	1pc	\$	280.00
31	Front panel <i>bu</i> /	1pc	\$	580.00
32	Fuso <i>bu</i> /	1pc	\$	115.00
33	Front wiper arm @\$115ea <i>lt</i> /	2pcs	\$	230.00
34	Front wiper blade @\$20ea <i>bu</i> /	2pcs	\$	40.00
35	Front wiper linkage	1pc	\$	370.00
36	Front wiper motor <i>X</i>	1pc	\$	430.00
37	Front center grille <i>bu</i> /	1pc	\$	600.00
38	Front corner panel rh <i>ca</i> /	1pc	\$	320.00
39	Front mirror stay rh <i>lt</i> /	1pc	\$	290.00
40	Front mirror glass <i>bu</i> /	1pc	\$	80.00

\$ 15,243.00

Add 15%

\$ 2,286.45

\$ 17,529.45

41	Front ERP bracket <i>bu</i> /	1pc	\$	15.00
42	Front number plate <i>lt</i> /	1pc	\$	30.00
	Sum Carried Forward		\$	17,574.45

Let Auto Care Plus help you
 be ready for the future.
 • Financing options available
 • In-store pickup and delivery service
 • Free price quote and estimate
 • Free loan quote and a "No Cost" program
 • Free loan counseling is offered
 • Repayment terms and conditions apply
 • See us for more information

Authorized by Dealer
 Signature
 Date

Handwritten notes:
 10 day
 15
 10/15/70
 10/15/70
 10/15/70

Sum Carried Forward

\$ 17,574.45

Labour Charge & Misc

Towing fee <i>receipt?</i>		\$	150.00 ?
To remove, repair, replace & install front damaged parts.	} }	\$	2,500.00 1800
To R & R wire harness		\$	180.00 60
To R & R front windscreen glass		\$	150.00 120
To remove & install door mechanism & check for function	} }	\$	180.00 80
To R & R front cabin unit <i>plugs?</i>		\$	900.00 400
To R & R air con system	}	\$	300.00 200?
To refill & top up air con gas	}		
To R & R front dashboard		\$	350.00 250
To putty & spray painting.		\$	1,000.00 800
Total		<u>\$</u>	<u>23,284.45</u>

All prices quoted are subjected to GST.

This is a computer generated document. No signature is required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Revised
 Hp 900/100/68
 10 days
 L/S
 08/06/23 @ 1630
 EXCESS: 600
 Revised
 Reviser after repair