

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 67228585
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2306-381-TG
DATE : 6-Jun-2023
VEHICLE REG. NO. : SJA8178U
VEHICLE MAKE : MERCEDES BENZ E200K 2008
CHASSIS NO. : WDB2110412B436063

TO Motor Claim Department
Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
1	Front Bumper <i>repair</i>	1	\$ 1,940.00	\$ 1,940.00
2	Front Bumper Retainer RH <i>X</i>	1	\$ 145.00	\$ 145.00
3	HeadLamp RH <i>X</i>	1	\$ 3,040.00	\$ 3,040.00
4	HeadLamp Bracket RH <i>X</i>	1	\$ 355.00	\$ 355.00
5	Front Bumper Garnish Chrome Trim RH <i>See</i>	1	\$ 155.00	\$ 155.00
6	Foglamp RH <i>X</i>	1	\$ 407.00	\$ 407.00
7	Foglamp Garnish RH <i>MIS</i>	1	\$ 55.00	\$ 55.00
8	Front Lower Grille <i>X</i>	1	\$ 75.00	\$ 75.00
9	Front Fender RH <i>repair</i>	1	\$ 1,045.00	\$ 1,045.00
Total Spare Parts				\$ 7,217.00
SPECIAL NETT				
10	Front Bumper Clips <i>X</i>	10	\$ 9.00	\$ 90.00
11	Front Fender Clips <i>X</i>	10	\$ 9.00	\$ 90.00
Total Special Nett				\$ 180.00
LABOUR				
12	Spray Painting Front Bumper, Front Fender Including Blending	1	\$ 600.00	\$ 600.00 <i>400</i>
13	Remove, Refit and Repair Affected Accident Parts	1	\$ 500.00	\$ 500.00 <i>300</i>
14	Check and Rectify Electrical Wiring	1	\$ 20.00	\$ 20.00
Total Labour				\$ 1,100.00
Amount Before Excess				\$ 8,497.00
Add GST @ 8%				679.76
Total Amount Payable				\$ 9,176.76

Estimate prepared by: RAZALI

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Razali
Hp 90010068
3 deep
4/5
14/06/23 @ 1435
Resy after repair