CS/EQI23005828/Tqy3 REF: ASS, REC. BY: Tayth EQ ASSIGNMENT

From: Date:	Veh No: SMA 42962 Yr Regn: 20/9, May
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Myota Pins co 178
at Workshop m/s	Colour A/C: Insured/Std/NI/NA
of	Sp.Reading 330 293 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	CINO: 5TDKB S F 4 5030 8 084
Clairns No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder/ Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder/Jammed/Leaked/Burnt or
Make of Veh:	Modl: Nit / S/Rim / STD A/Rim or /
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport	Tyre Size: F: LIZA / MIC / OHTSU / PIR / SUMI / R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or West fully Front Rear R/Bal. 6 mm R/Bal. 6 mm L/Bal. 6 mm D.O.A. D.O.I. 9/6/73 Survey held at Confort Curry Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or U/S / Curry The U/C / Chassis frame / Body Structure affected due to collision.
Taufikh finalised final fig \$880, 2 d	ays. (Red \$1397.81, 61%)
10/06 Typict	ays Of Repair: 2
i) 19/06 Typist : Final Report R	esurvey No. of Trip: 1 Survey Fee:
2) Add Fee:	: Site Insp (\$
	Interview (\$
Report Format : MER-TP	Tech Invo (8
Lump Com/LEJ: (\$ 880)	: Weel:end (%
	TOTAL

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

TP INSURER:

EQ Insurance Company Ltd (HQ)

CTPL

Singapore

Loke Wei Yieng

Pof: 305557015

PARTICULARS OF CLAIM

Claim Type:

THIRD PARTY

Ref. No:

Date of Loss: Driveable?

06/06/2023

Policy No:

Vehicle Reg. No.:

SHA4296L

UNKNOWN

Party At Fault:

Vehicle Reg. Date:

15/05/2019

Make/Model: Vehicle Colour:

BLUE

Engine No:

2ZR2C18243

TOYOTA PRIUS, 1.5 HYBRID (A)

Chassis No:

JTDKB3FU503080649

Odometer:

370294 KM

Paint Type:

List Item Discount:

25.00 %

Total Loss?

NO

Est. Duration of Repair

(day)

4

Remarks:

TEL: 62148355

Present Location:

COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS		Amount
Parts		1,137.81
Miscellaneous Items		0.00
Labour		1,140.00
Paintwork Labour		0.00
Towing		0.00
	Gross Total (S\$)	2,277.81
	+ GST 8.00% (S\$)	182.22
	Nett Amount (S\$)	2,460.03

This claim is handled by: MS. LOKE YY

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR D	DETAILS		
Referen	ce		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Jun 2023)	
Parts:	144	TOYOTA PRIUS 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	ComfortDelGro Engineering Pte Ltd/SHA4296L/08/06/2023 09:47		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers wit the END OF ESTIMATES marker on the last estimate page		
Further Info	: Items/values r	not in reference catalogue are prefixed with an asterisk *.	

Eat	tima	ton	on	Da	rtc
	IIIIa	LUS	OH	Га	12

	Qty Part No.	Particulars	%Disc	%Depr	Amount
1	1	*REAR BUMPER	25.00	0.00	€Y *503.04 FL
2	1	*REAR BUMPER CLIPS	25.00	0.00	× *22.00 FL
3	1	*REAR FENDER RH	25.00	0.00	€> *992.04 FL
F=Fra	anchise part. L=ListItemDisc.				
		Sub Total (S\$)			1,517.08
		 List Item Discount on L Items (S\$) 			379.27
		Total Parts (S\$)			1,137.81

ComfortDelGro Engineering Pte Ltd/SHA4296L/08/06/2023 09:47. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	3	Amount
Lab	our Items		700	
1	PANEL BEATING	New	350	400.00
2	SPRAY PAINTING CHARGE	New	500	600.00
3	REMOVE/ REFIX REVERSE SENSOR	New	30	60.00
4	TUFF KOTE	New	×	80.00
		Gross Labour Cost (S\$)		1,140.00

ComfortDelGro Engineering Pte Ltd/SHA4296L/08/06/2023 09:47. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tarphy 97495749

"Wh! 9/6/23 e 3 + 5 p

- Zdy,

Resuy after reposit

tarphy C lbhamp. wm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Mainline + 65 6383 6280 Facsimile + 65 6280 Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
08.06.2023 15:23

JOB CARD Sales Order: 5899483 JC NO305557015 ARC Repair TP(CLSO)1 eam: REGN NO.: MILEAGE TOMER SHA4296L COMFORT TRANSPORTATION PTE LTD FUEL MAKE MS TOYOTA 7010045 E.....1/2. TOMER NO. RESS 383 SIN MING DRIVE DATE/TIME IN MODEL PRIUS HYBRID(G4)08.06.2023 09:20 Singapore SINGAPORE 575717 65508755 YR OF MANU. 15.05.2019 TARGET DATE (O) (P) CHASSIS CODE JTDKB3FU503080649 COMPLETION DATE/TIME: COUNT CARD NO.

JOB DESCRIPTION


ccident Date: 06.06.2023

ATURE: 3P 06.06.2023

I/NO

LABOR CODE

DESCRIPTION



CKED & PASSED OUT BY:			
SERVICE ADVISOR			CUSTOMER'S SIGNATURE
wledgement Slip		Exit Pass	
:: • No.: SHA4296L	ΥΥ	Vehicle No.: SHA4296L	
of Service Advisor	Signature/Date	Name of Service Advisor	Date
returned to Service Reception upon c		To be kept by Security Guard	