



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)
UNKNOWN

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	13/05/2023
Vehicle Reg. No.:	SJJ6164A	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	SUZUKI SWIFT, 1.5 AT ABS AIRBAG 2WD (A)	Vehicle Reg. Date:	22/09/2008
Vehicle Colour:	WHITE		
Engine No:	M15A1326367	Chassis No:	JSAEZC21S00419530
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS	Amount
Parts	1,433.70
Miscellaneous Items	0.00
Labour	1,610.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	3,043.70
+ GST 8.00% (\$)	243.50
Nett Amount (\$)	3,287.20

This claim is handled by: JUNIOR

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS		
Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jun 2023)
Parts:	144	SUZUKI SWIFT 1.5 AT ABS AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJJ6164A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR DOOR RH (REPAIR)	0.00	0.00	-
2	1		*REAR FENDER RH (REPAIR)	0.00	0.00	-
3	1		*REAR BUMPER	0.00	0.00	*680.00 F
4	1		*REAR BUMPER RETAINER RH	0.00	0.00	*22.00 F
5	10		*REAR BUMPER CLIPS	0.00	0.00	*25.00 F
6	1		*REAR SPROT RIM RH	0	0.00	*480.00 FS
7	1		*REAR WHEEL BEARING RH	0.00	0.00	*140.00 F
Sub Total (\$\$)						1,347.00
+ Margin on L,N Items 10.00% (\$\$)						86.70
Total Parts (\$\$)						1,433.70

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out. Generated using Merimen e-Claims IEAS
--

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK & STRAIGHTEN REAR DOOR RH, REAR FENDER RH, REMOVE & REPLACE ACCIDENT DAMAGED PARTS, REALIGN ALL CONNECTION	New	700.00
2	SPRAY PAINT REAR DOOR RH, REAR FENDER RH, REAR BUMPER	New	700.00
3	REMOVE & REPLACE REAR UNDERCARRIAGE SUSPENSION RH	New	150.00
4	COMPUTER WHEEL ALIGNMENT	New	60.00
Gross Labour Cost (\$\$)			1,610.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >