

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	ICE LTD	F	Ref:	CS/INC23005834/Uvy3m4	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557	Γ	Date:	19/06/2023	
	ATTN: DAVID PHU	JA	C	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SKU 2904M	Veh. Inspected		FBS 8150Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1226023-002	Excess (\$)		0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		08/06/2023	
2.	2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA AEROX155	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	MH3SG6420MJ014506	Colour		BLACK	
	Odometer	17307 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	110-80-14	MAXXIS		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140-70-14	MAXXIS		6 mm	
	L/H Rear Tyre				mm	
4.	1. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
					1.	
5.	General Information					
	Accident Date	03/06/2023	Inspect Date / Ti	ime	08/06/2023 ( 10:41 AM )	
	Survey held at	ERZAT LEE MOTOR TRADING PTE LTD				
	25 KAKI BUKIT ROAD 4, #03-37, SYNERGY @ KB, SINGAPORE 417800					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					
	•					