



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897		Ref: CS3/AIS23005836/Anp3 Date: 08/06/2023 Code: AIS	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>			
<b>Insured Veh.</b>	SDK 8118L	<b>Veh. Inspected</b>	PC 743J
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	2023 32009104FR	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	SHANTI	<b>Assign Date</b>	07/06/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
<b>Accident Date</b>	04/06/2023	<b>Inspection Date</b>	08/06/2023
<b>Survey held at</b>	SIN FATT DIESEL MOTOR BLK 3020A UBI ROAD 1 #01-38 . SINGAPORE 408714		
<b>5a. Remarks</b>			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			