

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12
 Singapore 737856
 Tel: Fax: Email:

INSURER : INDIA INTERNATIONAL INSURANCE PTE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	
Policy No:	5098255312-05	Date of Loss:	05/06/2023
Vehicle Reg. No.:	SFF8768M	Driveable?	no
Driver Age:		Third Party Vehicle No.:	SLJ2236D
Any Injuries?	no	Contact No:	
Insured/Claimant:	WOO CHOOK HEY	Driver:	WOO CHOOK HEY

2.2
 78
 JA
 JA

PARTS MODEL

Make/Model:	Hyundai, Elantra 1.6 AT 4DR	Vehicle Reg. Date:	06/02/2018
	- KMHDH41		
Vehicle Colour:		Engine Number:	
Chassis No:	KMHD841CMJU629651	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	

42

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss COLLISION - HEAD TO REAR
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

*Not Notified
 1/1 Reg @
 Penny After Pain
 Kenneth
 96P10663
 2 days*

COST OF CLAIMS

	Amount
Parts	1,200.00
Miscellaneous Items	305.00
Labour	680.00
Paintwork Labour	720.00
Towing	0.00
Gross Total(S\$):	2,905.00
GST 7.00%(S\$):	203.35
Nett Amount(S\$):	3,108.35

This claim is handled by: Sky Toh T C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER	<i>Per</i> 680.00	-20.00	544.00 ✓
2	1	REAR BUMPER SIDE RETAINER LH	<i>Per</i> 45.00	-20.00	36.00 X
3	1	REAR BUMPER SIDE RETAINER RH	<i>Per</i> 45.00	-20.00	36.00 X
4	1	REAR BUMPER LOWER GARNISH	<i>Per</i> 350.00	-20.00	280.00 X
5	1	REAR END PANEL	<i>Per</i> 380.00	-20.00	304.00 X
Total Parts (\$\$)					<u>1,200.00</u>

Estimates of Miscellaneous Items

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	REAR BUMPER CLIPS (1 SET)	<i>Per</i> 45.00	0.00	45.00 ✓
2	1	REAR BUMPER SENSORS (1 SET)	<i>Per</i> 260.00	0.00	260.00 X
Sub Total (\$\$)					<u>305.00</u>

Estimates On Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Remove and Refit Rear Bumper Sensor.	80.00	0.00	80.00 <i>500</i>
2	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	600.00	0.00	600.00 <i>2000</i>
Gross Labour Cost (\$\$)					<u>680.00</u>

Estimates On Paint Work Labour

No.	Qty	Particulars	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	20.00	0.00	<i>Per</i> 20.00 X
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	700.00	0.00	700.00 <i>2200</i>
Gross Labour Cost (\$\$)					<u>720.00</u>

< END OF ESTIMATES >