



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

REPAIR PERFORMA INVOICE

TP Grab.
Ezlyn



Vehicle number	SNC9532R
Make / Model	HONDA VEZEL
Chassis number	RU31222936
Accident date	6/6/23
Reference	2306-08

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER <i>Del'd</i>	609.40 ✓
1	REAR BUMPER UNDERCOVER <i>Del'd</i>	143.00 ✓
2	REAR BUMPER REFLECTOR <i>RTA coach'd</i>	392.70 <i>196.35</i>
2	REAR BUMPER RETAINER <i>new</i>	48.20 +
4	TAILGATE WINDSCREEN MOULDING <i>new</i>	264.00 ✓ <i>155</i>
1	TAILGATE <i>Del'd</i>	1174.80 <i>1100</i>
1	TAILGATE LOCK <i>new</i>	191.40 ✓
1	TAILGATE LOCK STRIKER <i>new</i>	53.90 +
2	TAILGATE LAMP <i>cut</i>	1106.60 <i>800</i>
1	TAILGATE INNERTRIM BOARD <i>cut</i>	187.00 ✓
1	TAILGATE RUBBER <i>cut</i>	233.20 ✓
1	TAILGATE OUTER GARNISH <i>new</i>	258.50 +
1	TAILGATE INNER PULL COVER <i>new</i>	52.00 +
1	TAILGATE HONDA EMBLEM <i>new</i>	30.80 +
1	TAILGATE VEZEL EMBLEM <i>new</i>	42.90 ✓
1	END PANEL <i>Del'd</i>	497.20 ✓
1	END PANEL TOP GARNISH <i>Del'd</i>	71.50 ✓
1	KEYLESS SENSOR <i>cut</i>	184.00 ✓
1	KEYLESS ANTENNA <i>new</i>	198.80 +
1	SPARE TYRE TOP BOARD <i>Del'd</i>	231.00 ✓
1	SPARE TYRE TOOLS BOX <i>Del'd</i>	176.00 ✓
1	SPARE TYRE COMPARTMENT <i>new</i>	810.30 +
2	REAR WHEEL ARC GARNISH <i>RTA cut</i>	389.90 <i>194.95</i>
2	REAR FENDER INNER TRIM BOARD <i>RTA cut</i>	649.00 <i>324.50</i>
2	REAR TAILLAMP <i>cut</i>	1108.80 <i>950</i>
		9104.90
Less 20%		1820.98
Subtotal		7283.92
Balance C/F		7283.92
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1 SET	REAR BUMPER CLIP <i>new</i>	50.00 <i>30</i>
1 SET	TAILGATE INNER TRIM CLIP <i>new</i>	50.00 <i>35</i>
1 SET	REAR FENDER INNER TRIM CLIP <i>new</i>	50.00 <i>30</i>

6387.40

5109.92

1	REAR NUMBER PLATE <i>Best</i>	80.00 <i>50</i>
1	REAR WINDSCREEN SEALANT <i>n</i>	150.00 <i>60</i>
1	JOINT SEALANT <i>n</i>	150.00 <i>60</i>
1 set	REVERSE SENSOR <i>2nd</i>	200.00 <i>✓</i>
Subtotal		730.00
Balance C/F		8013.92
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
1	CHECK WIRING AND LIGHTINGS SYSTEM	120.00 <i>30</i>
2	REMOVE AND REFIT TRIM AND GARNISHES	150.00 <i>60</i>
3	REMOVE AND REFIT REAR REVERSE SENSOR	100.00 <i>50</i>
4	REMOVE AND RENEW WINDSCREEN GLASS	150.00 <i>120</i>
5	REMOVE AND REFIT TAILGATE ATTACHMENT	150.00 <i>60</i>
6	PANEL BEATING ON AFFECTED AREAS	1200.00 <i>800</i>
7	SPRAY PAINTING ON AFFECTED AREAS	1200.00 <i>800</i>
8	APPLY ANTI RUST ON AFFECTED AREAS	150.00 <i>60</i>
Subtotal		3220.00
Grand total		11233.92

Adnan G
1/s 08/06/23.

06 Days

total: 7549.92

1/s: GK

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: