



ESTIMATE

Date : 10/06/2023
To : ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
Attn. :
Office / Mobile :
Email Address :

From : GOLDBELL ENGINEERING PTE LTD
Attn. : LIEWSIMING
Office / Mobile :

Email / Fax No. : LiewSiMing@goldbell.com.sg

Reg No : GBF1714L
Model : FEA01BR1SDEB CBU AMT
Chassis No : FEA01BA20283
Engine No : 4P10C26231
Quotation No. : 183451
Ref. No. : GBE/SVC/SALES-HQ/120-0706
D.O.A. : 07/06/2023
Policy No. : D-23100784MFCV/4
Claim Type : TP CLAIM - ALLIANZ
INSURANCE
Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		GLASS,WINDSHIELD <i>cm</i>	1	1,125.00	-25	843.75	843.75
2		WEATHERSTRIP,WINDSHIELD <i>m</i>	1	626.52	-25	469.89	469.89
3		GARNISH,FR PANEL <i>sur</i>	1	764.60	-25	573.45	573.45
4		PANEL ASSY,CAB,FR <i>sur</i>	1	5,495.23	-25	4,121.42	4,121.42
5		MARK,FUSO <i>m</i>	1	268.74	-25	201.56	201.56
6		PANEL,CAB FR CORNER,LH <i>de</i>	1	882.48	-25	661.86	661.86
7		SEAL,CAB FR CORNER PANEL,LH <i>X</i>	1	64.29	-0	64.29	64.29
8		CAP,FR CORNER PANEL,LH <i>X</i>	1	51.81	-25	38.86	38.86
9		PANEL,CAB FR CORNER,RH <i>mcs</i>	1	882.48	-25	661.86	661.86
10		SEAL,CAB FR CORNER PANEL,RH <i>X</i>	1	64.29	-25	48.22	48.22
11		CAP,FR CORNER PANEL,RH <i>mcs</i>	1	51.81	-25	38.86	38.86
12		GRILLE,RADIATOR <i>cm</i>	1	762.17	-25	571.63	571.63
13		GROMMET,RADIATOR GRILLE <i>m</i>	8	6.68	-25	5.01	40.08
14		MARK,THREE-DIA <i>m</i>	1	143.97	-25	107.98	107.98
15		MARK,CANTER <i>m</i>	1	136.85	-25	102.64	102.64
16		BRACKET,RADIATOR GRILLE,CTR <i>X</i>	1	45.99	-25	34.49	34.49
17		HEADLAMP ASSY,LH <i>cm</i>	1	827.09	-25	620.32	620.32
18		GARNISH,HEADLAMP,LH <i>cm</i>	1	220.50	-25	165.38	165.38
19		HEADLAMP ASSY,RH <i>X</i>	1	827.09	-25	620.32	620.32
20		GARNISH,HEADLAMP,RH <i>X</i>	1	220.50	-25	165.38	165.38
21		LAMP ASSY,TURN SIGNAL,FR LH <i>cm</i>	1	446.09	-25	334.57	334.57
22		LAMP ASSY,TURN SIGNAL,FR RH <i>cm</i>	1	446.09	-25	334.57	334.57
23		STAY,RR VIEW MIRROR,LH <i>?</i>	1	799.20	-25	599.40	599.40
24		MIRROR,RR VIEW,LH <i>X</i>	1	165.60	-25	124.20	124.20
25		MIRROR,FR UNDER VIEW BLINDSPOT <i>RCM</i>	1	96.24	-25	72.18	72.18
26		STAY,RR VIEW MIRROR,RH <i>X</i>	1	764.37	-25	573.28	573.28
27		MIRROR,RR VIEW,RH <i>X</i>	1	165.60	-25	124.20	124.20
28		COVER,RR VIEW MIRROR STAY <i>X</i>	2	24.20	-25	18.15	36.30
29		HEATER ASSY <i>?</i>	1	3,149.21	-25	2,361.91	2,361.91
30		AIR INTAKE BOX,HEATER UNIT <i>?</i>	1	1,021.95	-25	766.46	766.46
31		PANEL ASSY,INSTRUMENT <i>?</i>	1	3,210.15	-25	2,407.61	2,407.61
32		LID,INSTRUMENT PANEL BRAKE FLUID <i>?</i> RESERVOIR	1	30.56	-25	22.92	22.92

ESTIMATE

Date :	10/06/2023	Reg No :	GBF1714L
To :	ALLIANZ INSURANCE SINGAPORE PTE. LTD.	Model :	FEA01BR1SDEB CBU AMT
Attn. :		Chassis No :	FEA01BA20283
Office / Mobile :		Engine No :	4P10C26231
Email Address :		Quotation No. :	183451
		Ref. No. :	GBE/SVC/SALES-HQ/120-0706
From :	GOLDBELL ENGINEERING PTE LTD	D.O.A. :	07/06/2023
Attn. :	LIEWSIMING	Policy No. :	D-23100784MFCV/4
Office / Mobile :		Claim Type :	TP CLAIM - ALLIANZ INSURANCE
Email / Fax No. :	LiewSiMing@goldbell.com.sg	Workshop :	8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
33		PANEL, INSTRUMENT ASSISTANT SIDE BIG ?	1	454.23	-25	340.67	340.67
34		PANEL, INSTRUMENT ASSISTANT SIDE SMALL ?	1	196.07	-25	147.05	147.05
35		FRAME, INSTRUMENT PANEL PASSENGER ?	1	400.20	-25	300.15	300.15
36		BRACKET, INSTRUMENT PANEL ? SIDE, PASSENGER	1	228.51	-25	171.38	171.38
37		FRAME, INSTRUMENT PANEL DRIVER ?	1	301.79	-25	226.34	226.34
38		BRACKET, INSTRUMENT PANEL SIDE, DRIVER ?	1	181.95	-25	136.46	136.46
39		SENSOR & ACTUATOR MODULE, CONTROL ? UNIT	1	2,980.00	-25	2,235.00	2,235.00
40		SUPPORT, SAM ?	1	358.43	-25	268.82	268.82
41		CLIP, INSTRUMENT PANEL UNDER TRIM ?	10	7.22	-25	5.42	54.15
42		LATCH & ACTUATOR, FR DOOR, LH ?	1	967.79	-25	725.84	725.84
43		LATCH & ACTUATOR, FR DOOR, RH ?	1	967.79	-25	725.84	725.84
44		TRIM, FR DOOR, LWR LH X	1	969.41	-25	727.06	727.06
45		TRIM, FR DOOR, LWR RH X	1	969.41	-25	727.06	727.06
46		DUCT, AIR CLEANER INTAKE ? cm ✓	1	1,108.82	-25	831.62	831.62

PARTS TOTAL : 25,527.28

SPECIAL NETT ITEMS

1	WINDSCREEN SEALANT ✓	2	60.00
2	IU BRACKET ✓	1	30.00

PARTS TOTAL: 110.00



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676

Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co Reg No: 198003963G

Page 3 / 4

ESTIMATE

Date	: 10/06/2023	Reg No	: GBF1714L
To	: ALLIANZ INSURANCE SINGAPORE PTE. LTD.	Model	: FEA01BR1SDEB CBU AMT
Attn.	:	Chassis No	: FEA01BA20283
Office / Mobile	:	Engine No	: 4P10C26231
Email Address	:	Quotation No.	: 183451
		Ref. No.	: GBE/SVC/SALES-HQ/120-0706
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 07/06/2023
Attn.	: LIEWSIMING	Policy No.	: D-23100784MFCV/4
Office / Mobile	:	Claim Type	: TP CLAIM - ALLIANZ INSURANCE
Email / Fax No.	: LiewSiMing@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE AND REFIX FRONT WINDSCREEN	120 150.00
2	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC @600	3000 4200.00
3	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	100 180.00
4	TO REMOVE AND REFIX FRONT DASHBOARD	300 800.00
5	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC @350	1400 1750.00

LABOUR TOTAL :	7,080.00
SUB-TOTAL :	32,717.28
GST @ 8% for \$ 32,717.28	2,617.38
GRAND TOTAL (S\$) :	35,334.66

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pass
Hp 900 10068
9 days
4/8
12/06/23 P1640
Reg after repair

FUSO AIRMAN.

biSAFE
STARK

