

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Krishnan Bhuvaneswari

Date: 09 Jun 2023

Preliminary Advice

Vehicle No	: SLZ2271S	Accident Date	: 30/05/2023
Make	: MAZDA 3	Policy No.	: D20MFL0000326_02
Assignment Date	: 09/06/2023	Excess	: S\$0.00
Date of Inspection	: 09/06/2023	Est. Duration of Repair	: 3
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) 205 BRADDELL ROAD SINGAPORE 579701		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,661.40
Revised Amount	:S\$	1,832.80
Check Items (Estimated)	:S\$	5,064.60
Total	:S\$	6,897.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	71,000.00
COE / PARF Rebate	:S\$	31,114.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,886.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.