

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: India International Insurance Pte Ltd  
6 Raffles Quay  
#22-00  
Singapore 048580From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Krishnan Bhuvaneswari

Date: 13 Jul 2023

**Preliminary Advice**

Vehicle No	: SLZ2271S	Accident Date	: 30/05/2023
Make	: MAZDA 3	Policy No.	: D20MFL0000326_02
Assignment Date	: 09/06/2023	Excess	: S\$750.00
Date of Inspection	: 09/06/2023	Est. Duration of Repair	: 3
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) 205 BRADDELL ROAD SINGAPORE 579701		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,909.20	(Estimate \$7,661.40 + Supplementary \$247.80)
Revised Amount	:S\$	2,080.60	
Check Items (Estimated)	:S\$	5,064.60	
Total	:S\$	7,145.20	
Lump Sum Repair	:S\$		

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	71,000.00
COE / PARF Rebate	:S\$	31,114.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,886.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.