

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0544/2023/EQ
DATE : 8-Jun-23
WIP : 24146

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/6/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR HARISH PRABHAKARAN NAMBIAR
ADDRESS : 12 TAO CHING ROAD
#14-27
SINGAPORE 618726
TELEPHONE : HP +65 81391879
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210032831-01
VEHICLE NO : **SJZ 4618 L**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 1/4/2021
ENGINE NO : DKY 015299
CHASSIS NO : WAUZZZF27MN057960
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 7-Jun-23
PLACE OF ACCIDENT : YUAN CHING ROAD



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJZ 4618 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 800.00 ✗	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,600.00 ✗	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00 ✗	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,800.00 ✗ 500	
6	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,500.00 ✗ 550	
TOTAL LABOUR CHARGES		: \$ 11,380.00	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJZ 4618 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO CARRY OUT CALIBRATION FOR FRONT CAMERA 360 DEGREE.	S/N \$	480.00	?
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$	<u>12,052.00</u>

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 4618 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Del'd</i>	1	\$ 3,187.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 689.00	✓
3	FRONT BUMPER CLOSING ELEMENT - CENTER <i>new</i>	1	\$ 263.00	✓
4	FRONT BUMPER ADAPTER - LH / RH	2	\$ 94.00	✓
5	FRONT BUMPER REINFORCEMENT - LH / RH	2	\$ 264.00	✓
6	FRONT BUMPER GRILLE - LOWER CENTRE <i>new</i>	1	\$ 181.00	✓
7	FRONT BUMPER CLOSING ELEMENT - LOWER <i>new</i>	1	\$ 248.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 1,026.00	✓
9	FRONT BUMPER AIR GUIDE - LH / RH INNER <i>new</i>	2	\$ 78.00	✓
10	FRONT BUMPER AIR GUIDE - LH / RH OUTER	2	\$ 62.00	✓
11	RADIATOR GRILLE <i>Del'd (Photo)</i>	1	\$ 2,603.00	✓
12	RADIATOR GRILLE COVER	1	\$ 65.00	✓
13	RADIATOR GRILLE COVER CAP <i>new</i>	1	\$ 59.00	✓
14	RADIATOR GRILLE BRACKET	1	\$ 111.00	✓
15	RADIATOR GRILLE SECURING PLATE	1	\$ 99.00	✓
16	FRONT "360" CAMERA	1	\$ 1,115.00	✓
17	FRONT "360" CAMERA ADAPTER CABLE LOOM	1	\$ 464.00	✓
18	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 598.00	✓
19	FRONT PARKING AID SEAL RING	4	\$ 11.00	✓
20	FRONT BUMPER WIRING SET	1	\$ 648.00	✓
SUB TOTAL SPARE PARTS		:	\$ 11,865.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 4618 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN LOW TONE - LH	1	\$ 244.00	+
22	HORN HIGH TONE - RH	1	\$ 157.00	+
23	HORN BRACKET - LH / RH	2	\$ 112.00	+
24	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 1,140.00	?
25	FRONT BUMPER SUPPORT - LH / RH	2	\$ 71.00	?
26	FRONT BUMPER FOAM FILLER PIECE	1	\$ 267.00	?
27	FRONT BUMPER BRACKET - LH / RH	2	\$ 130.00	?
28	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 106.00	+
29	FRONT BUMPER TOP COVER	1	\$ 149.00	+
30	CAUTION SIGN STICKER	1	\$ 17.00	+
31	OIL COMPLY WITH VW STANDARD STICKER	1	\$ 14.00	+
32	AIR CONDITIONER STICKER	1	\$ 36.00	+
33	BONNET	1	\$ 5,971.00	+
34	BONNET IMPACT PROTECTION - CENTER	1	\$ 53.00	+
35	BONNET IMPACT PROTECTION - RH	1	\$ 24.00	+
36	BONNET IMPACT PROTECTION - LH	1	\$ 22.00	+
37	BONNET STRIKER - LH / RH	2	\$ 260.00	+
38	BONNET LOCK - LH / RH	2	\$ 387.00	+
39	BONNET RELEASE ELEMENT	1	\$ 69.00	+
40	BONNET RELEASE LEVER	1	\$ 16.00	+
SUB TOTAL SPARE PARTS		:	\$ 9,245.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 4618 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET BOWDEN CABLE - CENTER	1	\$ 67.00	+
42	BONNET RELEASE CABLE COVER	1	\$ 12.00	+
43	HEADLIGHT MOUNTING - LH / RH	2	\$ 280.00	+
44	HEADLIGHT - LH / RH	2	\$ 19,424.00	+
45	LIFT CYLINDER - LH / RH	2	\$ 460.00	+
46	LIFT CYLINDER BRACKET - LH / RH	2	\$ 16.00	+
47	LIFT CYLINDER HOSE	1	\$ 208.00	+
48	BONNET LOCK COVER - LH / RH	2	\$ 104.00	+
49	LOCK CARRIER	1	\$ 1,448.00	+
50	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 27.00	+
51	A/C CONDENSER WITH DRYER	1	\$ 724.00	+
52	READY-MIX COOLANT	6	\$ 326.00	+
53	RADIATOR AIR GUIDE - LH / RH	2	\$ 100.00	+
54	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 78.00	+
55	FRONT NUMBER PLATE	S/N	\$ 60.00	✓
56	SUNDRIES		\$ 600.00	?
TOTAL SPARE PARTS		:	\$ 45,044.00	
TOTAL LABOUR CHARGES		:	\$ 12,052.00	
GRAND TOTAL		:	\$ 57,096.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian L
09/06/23

Not Authorized, 03 Days.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT