



Policy No : D21MFL0000447_02

Date: 13th June 2023

Our Ref : CS/GRB23005883/Kqy3m4

M/s India International Insurance Pte Ltd

64 Cecil Street

#05-02 IOB Building

Singapore 049711

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLQ 8117M
ACCIDENT ON 06/06/2023**

Instruction was received to inspect the vehicle Reg. No. SLQ 8117M. The inspection was conducted on 09/06/2023 at the premises of M/s Esteem Performance Pte Ltd, 385 Sin Ming Drive, Singapore 575718.

The following vehicle information was recorded:

Registration Number	: SLQ 8117M
Make/Model	: Honda Vezel 1.5X Hybrid A
Year of Registration	: 2017
Body Colour	: Metallic Grey
Chassis Number	: RU31248437
Engine Capacity	: 1496 cc
Speedometer Reading	: 512507 km

The vehicle sustained damages at the front portion. The chassis frame and body structure affected due to collision. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 65,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 24,136.00)
Nett Liability	<u>S\$ 40,864.00</u> =====

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.