

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	LONPAC INSURAN	ICE BHD		Ref:	CS3/LPC23005892/Rny3
	300 BEACH ROAD			Date:	09/06/2023
	#17-04/07 THE CO	NCOURSESINGAPORE 199555			1 B00
				Code:	
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	YN 9951B	Veh. Inspected		PC 3042D
	Policy No.		Coverage (\$)		0.00
	Claim No.	22/23/23/VC05/027478	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		09/06/2023
2. Vehicle Particulars & Condition					
	Make & Model		c.c		0
	Engine No.	HIDDEN	Year of Reg.		
	Chassis No.		Colour		
	Odometer	-	Steering		
	Brakes		Modification		
	General				
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre				mm
	L/H Front Tyre				mm
	R/H Rear Tyre				mm
	L/H Rear Tyre				mm
4.	Description of Damages				
5.	General Information				
	Accident Date	15/05/2023	Inspection Date	)	09/06/2023
	Survey held at	LAY AUTO GARAGE PTE LTD			
		38 TOH GUAN ROAD EAST #01-56 ENTERPRISE HUB SINGAPORE 608581			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				