

ASS. REC. BY:

REF:

TMI /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

837,845/-

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 5991R

Yr Regn:

12, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

C.C

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

269401

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3FU 403077 290

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / Rim or

Tyre Size:

F: Warrli 195/65R15

R: Pailun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

8

mm

L/Bal.

6

mm

L/Bal.

8

mm

D.O.A.

7/6/23

D.O.I.

8/6/2023

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S FM

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Not Withheld
L1 Imp &

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5991R

AAD2306-

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

08 JUN 2023

SHD5991R

JTDKB3FU403077290

200303878K

TOYOTA

PRIUS

7/6/2023

YN1576D/ To Kio.

12/12/2018

PART

LIST

1 COVER, FRONT BUMPER	\$	72	653.31	✓
1 ABSORBER, FRONT BUMPER ENERGY	\$	CM	100.17	✓
1 REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	R	902.16	✓
1 EXTENSION, FRONT BUMPER, LH	\$	R	151.41	X
1 EMBLEM ASSY, RADIATOR GRILLE	\$	R	114.98	✓
1 GRILLE SUB-ASSY, RADIATOR	\$	R	436.38	X
1 GRILLE, RADIATOR, LOWER NO.1	\$	R	214.41	X
1 COVER, FRONT BUMPER HOLE, LH	\$	R	37.07	X
1 STAY SUB-ASSY, FRONT BUMPER, LH	\$	R	59.85	✓
1 BRACKET, FRONT BUMPER SIDE, LH	\$	R	74.97	✓
1 LOUVER SUB-ASSY, COWL TOP VENTILATOR	\$	Not in	865.83	✓
1 PROTECTOR, COWL TOP VENTILATOR LOUVER	\$	R	20.58	✓
1 PANEL, INSTRUMENT PANEL FINISH, END RH	\$		146.37	✓
1 GLASS, WINDSHIELD	\$	CM	1,993.53	✓
1 MOULDING, WINDSHIELD, OUTSIDE RH	\$	R	107.73	✓
1 HOOD SUB-ASSY	\$	R	1,243.20	✓
1 LOCK ASSY, HOOD	\$	R	170.31	X
1 HINGE ASSY, HOOD, LH	\$	R	74.34	✓
1 HINGE ASSY, HOOD, RH	\$	R	74.34	✓
1 LAMP ASSY, FOG, LH	\$	Not in	1,200.78	✓
1 UNIT ASSY, HEADLAMP, LH	\$	R	3,325.56	✓
1 COVER SUB-ASSY, FRONT PILLAR, UPR RH	\$	R	126.74	✓
1 FENDER SUB-ASSY, FRONT LH	\$	R	1,236.69	✓
1 BRACE SUB-ASSY, FENDER APRON, RH	\$	R	368.24	X
1 APRON ASSY, FRONT FENDER, RH	\$	R	222.71	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2306-

SHD5991R

- 1 EMBLEM, SIDE PANEL LH
- 1 LINER, FRONT FENDER, LH
- 1 RIM

\$	<i>me</i> 68.88 ✓
\$	<i>Tn</i> 255.36 ✓
\$	<i>in</i> 1,995.11 X
TOTAL \$	16,240.99
25% \$	4,060.25
\$	12,180.74

Special Nett

- 1 FRT BUMPER CLIP
- 1 FENDER CLIP
- 1 FENDER LINER CLIP
- 1 FRT LH BUMPER RETAINER CLIP
- TOTAL**

\$	<i>me</i> 65.00 <i>65.00</i>
\$	<i>nn me</i> 130.00 X
\$	<i>me</i> 130.00 <i>65.00</i>
\$	<i>nn</i> 65.00 X
\$	390.00

TOTAL PARTS \$ 12,570.74**LABOUR**

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 *500*

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 *800*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 *60*

To Check Electrical Lighting Concerned.

\$ 170.00 *20*

TOTAL \$ 3,590.00**Over All Total \$ 16,160.74**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting (PART-BY-PART) Repair Days
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

08 days
4 days

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/06/2023 16:56 (SGT)
Reported by	Actual Driver
Date of Accident	07/06/2023 11:40 (SGT)
Exact Location of Accident	Near 98 Waterloo St, Singapore
Additional Location Information	OUTSIDE 96 WATERLOO ST
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHD5991R

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Company Reg No	2XXXXX878K
Email Address	claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62876666
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	HSBC Life (Singapore) Pte. Ltd
Policy Number / Cover Note Number	VFX/P2413997

DRIVER

Name of Driver	TAY CHOON LENG
NRIC No	SXXXX348C
Date Of Birth	08/06/1954
Occupation	Outdoor

Date Of Driving Pass	01/08/1979
Driving experience	43 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97504369
Alt. Phone Number	-
Email Address	claims@transcab.com.sg
Address	476 SEMBAWANG DR
Address complement	#05-309
Postcode	750476
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT


ON 07/6/2023 AT ABOUT 1140HOURS , I WAS TRAVELLING ALONG WATERLOO ST TOWARDS MIDDLE ROAD . WHEN I DRIVING AT THE MOST LEFT LANE , SUDDENLY VEHICLE B REVERSING OUT FROM 161 MIDDLE ROAD WITHOUT CHECKING AND COLLIDED ONTO LEFT SIDE OF MY VEHICLE .

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN1576D
Vehicle Manufacturer	Mitsubishi
Vehicle Model	FE83BE6SRDEA
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFIED BY ALAN MARS (ARC)
REPORTING OFFICER
WONG JUN KEAT

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

878K

Vehicle Details

Vehicle No.:

SHD5991R

Vehicle to be Exported:

Yes

Intended Deregistration Date:

07 Jun 2023

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS 5DR HATCHBACK (AUTO)

Primary Colour:

Red

Manufacturing Year:

2018

Engine No.:

2ZR2B79786

Chassis No.:

JTDKB3FU403077290

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$26,605.00

Original Registration Date:

12 Dec 2018

First Registration Date:

12 Dec 2018

Transfer Count:

0

Actual ARF Paid:

\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

11 Dec 2026

PARF Rebate Amount:

\$10,685.00

Intended COE Rebate Details

COE Expiry Date:

11 Dec 2026

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

QPP Paid:

\$22,057.00

COE Rebate Amount:

\$9,679.00

Total Rebate Amount:

\$20,364.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

Information contained herein is correct as at 07 Jun 2023

OK