

(08/11/13) wef

ASS. REC. BY: Paul

REF:

CS/LPC 23005895/RK3

653M

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SIN 63472

at Workshop m/s

SBS TRANSIT

of

28, BRON LK ST -

Insured:

LPC

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SIN 63472

Yr Regn: 221 / 004

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

ALEXANDER DENNIS SUV

C.C. 7698

Colour:

GREEN

A/C: Insured / Std / NI / NA

Sp. Reading

109642

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SFD 323CR/LCZ40053

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

305/60R22.5

R:

- d/p

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8/8

mm

L/Bal.

8

mm

L/Bal.

8/8

mm

D.O.A.

29/05/23

D.O.I.

09/06/23

Survey held at

SBS TRANSIT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Submit front fig & 2274.94, 3 days. (Red & 0.7, 0.2)

Date/Time, File Pass to?

☐

: Prel. Report

1) 17/7/23

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

2274.94



SBS Transit Ltd
Soon Lee Depot
28 Soon Lee Road Singapore 628083

Mainline +65 6284 8866
Facsimile +65 6262 3055

www.sbstransit.com.sg

Company Registration No: 199208653M

DATE: 15.07.2023
DAY : Saturday

Workshop Accident Repair Estimate
FOR SURVEYOR ONLY

ACCIDENT DATE 29.05.2023 BUS REGISTRATION NUMBER SG6347Z
ACCIDENT TIME 21:49 HRS BUS TYPE (DD OR SD) DD
THIRD PARTY CLAIM AGAINST LORRY, YN5180K. DATE of SURVEY

S/No	SECTION A :	PARTS & MATERIAL COST	
	SG6347Z, ADL E500 EU6, DD, AC, 3-Door, 3 Axle.		
	Part or Item Description	Quantity	Total Cost
1	30117949, SIDE GLASS.LS.OS.4MM.TOUGHENED <i>bro /</i>	1 pc	\$ 601.64
2	30750114, SIKI 206 G+P PRIMER.1 LITRE TIN. <i>m /</i>	1 pc	\$ 162.50
3	99001048, SIKAFLEX 255 EXTRA BLACK (400 MLSAU). <i>m /</i>	2 pcs	\$ 31.20
4	LAST ITEM		\$ -
5			\$ -
6			\$ -
7			\$ -
8			\$ -
9			\$ -
10			\$ -
11			\$ -
12			\$ -
13			\$ -
14			\$ -
15			\$ -
TOTAL PARTS & MATERIAL COST			\$ 795.34

	SECTION B :	ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)	
	FOR WORKSHOP ONLY.....		
	Labour		\$ 1,479.60
	Spray Painting		
	Vinyl		
	Advertisement		
			\$ -
TOTAL LABOUR COST			\$ 1,479.60

	SECTION C :	SUMMARY	
TOTAL REPAIR COSTS			\$ 2,274.94
TOTAL DOWNTIME			3.0 days

NOTE:

- 1) Repair cost is excluding Loss of use.
- 2) Additional parts might be required during the course of repair.