

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AUTOMOTIVE EN	GRG. & MGT. DIVISION (TP)		Ref:	CS/SPF23005896/Kny3m4	
	FORCE) POLICE L	S SECTION (SPORE POLICE OGISTICS BASE (PLB) 1 SINGAPORE 438675		Date:	27/06/2023	
	ATTN: LAI PENG C	CHONG		Code:	SPF	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GZ 3263T	Veh. Inspected		SJM 9032L	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	ACS/105/009/2023/038	Excess (\$)		0.00	
	Assign From	LAI PENG CHONG	Assign Date		09/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA VIOS (A)	c.c		1497	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	MR053HY9305096103	Colour		METALLIC BEIGE	
	Odometer	229300 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/55R15	MICHELIN		5 mm	
	L/H Front Tyre	195/55R15	MICHELIN		5 mm	
	R/H Rear Tyre	195/55R15	BLACKLION		6 mm	
	L/H Rear Tyre	195/55R15	BLACKLION		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	07/06/2023	Inspection Date	•	12/06/2023	
	Survey held at AUTHORIZE WORKSHOP PTE LTD					
		160 SIN MING DRIVE #03-19, SIN MING AUTOCITY, SINGAPORE 575722				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				