

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

LIBERTY INSURANCE PTE LTD

51, Club Street # 03 - 00
 Liberty House
 Singapore 069428
 Tel : 1800-542 3789 / 6328-0611
 Fax : 6224 / 1047

Quotation

DATE : 25.05.2023
 VEH NO : SLP9510J
 MODEL : Toyota Altis
 D O A : 24.05.2023
 YR REF : SNE6258S

Veron

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLP9510J (TOYOTA ALTIS)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Reis</i>	1	589.60 +
2	Front Bumper Side Holder <i>Neu</i>	1	55.10 +
3	Head Lamp <i>Neu</i>	1	2,843.20 +
4	Front Fender <i>Dented</i>	1	698.40 ✓
5	Front Fender Inner Shield <i>Dented</i>	1	159.30 ✓
6	Emblem <i>Neu</i>	1	58.60 ✓
7	Front Door <i>Distorted</i>	1	1,359.30 ✓
8	Front Door Lock <i>Neu</i>	1	371.20 +
9	Front Door Weatherstripe <i>Neu</i>	1	195.50 +
10	Front Door Hinges <i>Green</i>	2	159.00 +
11	Front Door Checker <i>Dented</i>	1	69.10 +
12	Front Door Inner Trim Board <i>Dented</i>	1	681.70 ✓
13	Front Door Glass Regulator Gear <i>Reis</i>	1	225.90 ✓
14	Front Door Glass Regulator Motor <i>Neu</i>	1	450.10 +
15	Front Door Wing Mirror <i>Neu</i>	1	1,197.10 +
16	Rocker Panel <i>Dented</i>	1	856.90 ✓
17	Rear Door <i>Dented</i>	1	1,347.20 ✓
18	Rear Door Lock <i>Neu</i>	1	385.80 +
19	Rear Door Weatherstripe <i>Neu</i>	1	191.40 +
20	Rear Door Hinges <i>Green</i>	2	158.20 +
21	Rear Door Checker <i>Dented</i>	1	65.90 +
22	Rear Door Inner Trim Board <i>Dented</i>	1	634.20 ✓
23	Rear Door Glass Regulator Gear <i>Neu</i>	1	239.40 +
24	Rear Door Glass Regulator Motor <i>Neu</i>	1	430.10 +
25	Rear Fender <i>Reis</i>	1	1,091.10 +
26	Rear Fender Inner Shield <i>Neu</i>	1	169.20 +
27	Rear Bumper <i>Lois</i>	1	545.70 +
28	Rear Bumper Side Holder <i>Neu</i>	1	48.40 +
29	Front Wheel Rim <i>Art.</i>	1	2,173.50 <i>800(SN)</i>

Item	Description	Qty	Amt
30	Front Lower Arm	1	471.50 +
31	Front Shock Absorber	1	438.80 +
32	Front Knuckle Arm	1	487.20 +
33	Front Wheel Hub c/w Bearing	1	241.70 +
34	Rear Wheel Rim <i>Cot</i>	1	2,173.50 <i>800 (300)</i>
35	Rear Axle	1	2,466.20 +
36	Rear Wheel Hub c/w Bearing	1	444.90 +
37	Rear Shock Absorber	1	344.20 +

6567.20

4925.40

S.N. 1600

Less 20%

25%

S/NET ITEMS

1	Front Bumper Clips	1	\$ 30.00 +
2	Front Fender Inner Shield Clips	1	\$ 30.00 ✓
3	Front Door Inner Trim Board Clips	1	\$ 30.00 ✓
4	Front Door Black Tape	1	\$ 60.00 ✓
5	Front Door Visor	1	\$ 100.00 <i>80</i>
6	Rear Door Inner Trim Board	1	\$ 30.00 ✓
7	Rear Door Black Tape	1	\$ 60.00 ✓
8	Rear Door Visor	1	\$ 100.00 <i>80</i>
9	Rear Fender Inner Shield Clips	1	\$ 30.00 +
10	Rear Bumper Clips	1	\$ 30.00 ✓
11	Front Tyre	1	\$ 250.00 +
12	Rear Tyre	1	\$ 250.00 +
			\$ 1,000.00

Total parts

\$ 20,614.48

LABOUR CHARGE

1	To knocking & pull out LH side portion & renew above parts	1,800.00 <i>1200</i>
2	To putty & spray up paint works	1,600.00 <i>1400</i>
3	To check wiring	100.00 <i>30</i>
4	To remove upholstery	150.00 <i>50</i>
5	To remove reverse sensor	100.00 <i>50</i>
6	To remove rear windscreen	180.00 <i>+</i>
7	To transfer front and rear door fittings	300.00 <i>160</i>

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
8	To remove front undercarriage		350.00 +
9	To remove rear undercarriage		450.00 +
10	To perform wheel alignment		150.00 80
			5,180.00
Grand Total			\$ 25,794.48

2970

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 8895.40

L/S: 7.91c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: