



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23005908/Uqp3m4 Date: 10/07/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 4478L	Veh. Inspected	SKT 8487R	
Policy No.		Coverage (\$)	0.00	
Claim No.	AVS23/1828	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	08/06/2023	
2. Vehicle Particulars & Condition				
Make & Model	SUBARU XV (A)	c.c	1600	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	JF1GP3KC5FG152586	Colour	ORANGE	
Odometer	111376 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/55 R17	CONTINENTAL	6 mm	
L/H Front Tyre	225/55 R17	CONTINENTAL	6 mm	
R/H Rear Tyre	225/55 R17	CONTINENTAL	6 mm	
L/H Rear Tyre	225/55 R17	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/06/2023	Inspection Date	09/06/2023	
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840			
5a. Remarks				
A)REGISTRATION DATE: 25 JUN 2015 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	