



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807			Ref: CS3/MSG23005910/Tqy3e2 Date: 16/06/2023 Code: MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SFY 3419D	Veh. Inspected	SMY 735C
	Policy No.	1001371967	Coverage (\$)	0.00
	Claim No.	316062	Excess (\$)	0.00
	Assign From	CRYSTAL LEE	Assign Date	09/06/2023
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	KMHLN41ETMU094600	Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	30/05/2023	Inspection Date	12/06/2023
	Survey held at	Blk 3012 Bedok Industrial Park E #01-2016		
	Repairer	YK SUPREME AUTOWERKZ PTE LTD		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			