



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO23005911/Any3m4 Date: 25/07/2023 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBU 6900D	Veh. Inspected	SLT 6114T	
Policy No.	D23MTMC01000702	Coverage (\$)	0.00	
Claim No.	CMTD2302330/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	09/06/2023	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI ELANTRA	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	KMHD841CMJU570554	Colour	BLUE	
Odometer	38231 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	MICHELIN	6 mm	
L/H Front Tyre	215/45 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/45 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/06/2023	Inspection Date	12/06/2023	
Survey held at	ADVANCE AUTO GARAGE 23 KAKI BUKIT AVENUE 4, #04-01 VICOM KAKI BUKIT INSPECTION CENTER, SINGAPORE 415933.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	