

ADVANCE AUTO GARAGE

10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE
SINGAPORE 417868
TEL: 90079247

VEHICLE DETAILS

VEHICLE NO : SLT6114T 2017 NOV
VEHICLE MODEL : HYUNDAI ELANTRA
CHASSIS NO : KMHD841CMJU570554

TP Sampo.
Hui Rong.

ACCIDENT DETAILS

DATE :
TIME :

THIRD PARTY REQUESTOR / CONTACT : XAIVER / 90079247

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL	
1	REAR BUMPER <i>Defect</i>	1	\$ 495.60	\$ 495.60	✓
2	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 92.30	\$ 184.60	✓
3	REAR BUMPER REINFORCEMENT <i>Defect</i>	1	\$ 329.60	\$ 329.60	✓
4	REAR BUMPER REINFORCEMENT STAY <i>new</i>	2	\$ 145.80	\$ 291.60	✓
5	REAR BUMPER REINFORCEMENT BRACKET <i>new</i>	5	\$ 18.00	\$ 90.00	✓
6	REAR BUMPER REINFORCEMENT ANTENNA SENSOR <i>Defect</i>	1	\$ 195.50	\$ 195.50	✓
7	REAR BUMPER SIDE UNDERCOVER <i>new</i>	2	\$ 98.60	\$ 197.20	✓
8	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 72.50	\$ 145.00	✓
9	REAR END PANEL <i>Defect</i>	1	\$ 569.40	\$ 569.40	✓
10	REAR END PANEL TOP GARNISH <i>Defect</i>	1	\$ 215.60	\$ 215.60	✓
11	TAILLAMP <i>3 m</i>	2	\$ 598.60	\$ 1,197.20	✓
12	TAILLAMP PANEL <i>3 m</i>	2	\$ 188.90	\$ 377.80	✓
13	BOOTLID <i>Defect</i>	1	\$ 1,782.10	\$ 1,782.10	✓
14	BOOTLID LOCK <i>new</i>	1	\$ 166.70	\$ 166.70	✓
15	BOOTLID LOCK STRIKER <i>new</i>	1	\$ 45.20	\$ 45.20	✓
16	BOOTLID WEATHERSTRIP <i>new</i>	1	\$ 178.60	\$ 178.60	✓
17	BOOTLID REFLECTOR <i>new</i>	2	\$ 402.90	\$ 805.80	✓
18	BOOTLID INNER TRIM <i>new</i>	2	\$ 246.80	\$ 246.80	✓
19	BOOTLID HINGE <i>new</i>	2	\$ 89.60	\$ 179.20	✓
20	BOOTLID NUMBER PLATE LAMP <i>new</i>	2	\$ 45.20	\$ 90.40	✓
21	HYUNDAI LOGO <i>3 m</i>	1	\$ 55.90	\$ 55.90	✓
22	ELANTRA WORDING <i>3 m</i>	1	\$ 48.90	\$ 48.90	✓
23	SPARE TYRE TOP COVER <i>new</i>	1	\$ 298.60	\$ 298.60	✓
24	REAR EXHAUST PIPE <i>3 m</i>	1	\$ 695.70	\$ 695.70	✓
25	REAR EXHAUST PIPE MOUNTING <i>3 m</i>	1	\$ 45.20	\$ 45.20	✓
26	REAR EXHAUST PIPE GASKET <i>1 m</i>	1	\$ 39.60	\$ 39.60	✓

TOTAL PRICE: \$ 8,967.80
LESS 20% \$ 1,793.56
SUB TOTAL PRICE: \$ 7,174.24

3854.30

3087.44

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>3rd</i>	1	\$ 30.00	\$ 30.00
2	REAR NUMBER PLATE HOLDER <i>3rd</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
4	REAR BUMPER LOWER SPOILER <i>Damaged</i>	1	\$ 1,000.00	\$ 1,000.00
5	REAR BUMPER LOWER SPOILER SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
6	REAR BUMPER SIDE UNDERCOVER CLIPS <i>new</i>	2 SETS	\$ 20.00	\$ 40.00
7	REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00
8	REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00
9	REVERSE SENSOR <i>Damaged</i>	1 SET	\$ 280.00	\$ 280.00
10	REAR CAMERA <i>new</i>	1	\$ 480.00	\$ 480.00
11	BOOTLID INNER TRIM CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00
12	REAR EXHAUST TAIL PIPE (DUMMY) <i>new</i>	2	\$ 150.00	\$ 300.00

Bootlid Top Spoiler

800 500

TOTAL : \$ 2,360.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	<i>800</i>	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	<i>800</i>	
3	WIRING CHECK	\$ 100.00	<i>30</i>	
4	TO APPLY TUFF COAT	\$ 150.00	<i>60</i>	
5	TO REMOVE REVERSE SENSOR	\$ 100.00	<i>50</i>	
6	TO REMOVE REAR CAMERA	\$ 100.00	<i>50</i>	
7	TO REMOVE UPHOLSTERY	\$ 150.00	<i>60</i>	
8	TO TRANSFER BOOTLID FITTINGS	\$ 150.00	<i>60</i>	
9	TO REMOVE EXHAUST PIPE	\$ 150.00	<i>x.</i>	

TOTAL: \$ 3,300.00

1910

ESTIMATE REPORT

TOTAL PARTS COST: \$ 9,534.24

TOTAL LABOUR COST: \$ 3,300.00

TOTAL REPAIR COST: \$ 12,834.24

total: 6397.44

W/s: 5.1K.

06 Days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5,100 6 days

5,100 6 days