

TP INSURER: India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	08/06/2023
Vehicle Reg. No.:	SNK3640J	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	Muhammad Faizal Bin Jumari	Driver (Insured):	Jahangir Md Mohiuddin

Make/Model:	TOYOTA RAIZE, 996cc (A)	Vehicle Reg. Date:	06/04/2023
Vehicle Colour:	White		
Engine No:	1KRK131930	Chassis No:	A200A0117861
Odometer:	0 KM		

Paint Type:

List Item Discount: 25.00 %

Total Loss? NO

Est. Duration of Repair (day) 8/6 days

*Not Authorized
Repair By claim*

Remarks: VEHICLE IS IN

Present Location: CITY AUTO PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	8,674.65
Miscellaneous Items	1,246.00
Labour	2,660.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	12,580.65
+ GST 8.00% (\$\$)	1,006.45
Nett Amount (\$\$)	13,587.10

This claim is handled by: VRONICA

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Jun 2023)
 Parts: M1-SUV TOYOTA RAIZE 996cc (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: City Auto Pte Ltd/SNK3640J/12/06/2023 10:36
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Tailgate	25.00	0.00	CM *2,387.00 FL	✓
2	1		*Tailgate weatherstrip	25.00	0.00	DIS/CM *359.90 FL	✓
3	1		*Tailgate lock	25.00	0.00	CM *650.40 FL	✓
4	1		*Tailgate striker	25.00	0.00	CM *78.90 FL	✓
5	2		*Tailgate lamp	25.00	0.00	CM *671.60 FL	✓
6	1		*Tailgate outer garnish	25.00	0.00	CM *204.50 FL	✓
7	1		*Tailgate logo	25.00	0.00	CM *72.20 FL	✓
8	2		*Taillamp	25.00	0.00	CM *1,362.80 FL	✓
9	1		*Rear LH wheel arch garnish	25.00	0.00	CM *162.90 FL	✓
10	1		*Rear bumper	25.00	0.00	CM *1,125.80 FL	✓
11	2		*Rear bumper retainer	25.00	0.00	CM *179.00 FL	✓
12	12		*Rear bumper clip	25.00	0.00	CM *58.80 FL	✓
13	1		*Rear bumper lower diffuser	25.00	0.00	CM *407.30 FL	✓
14	2		*Rear bumper side cover	25.00	0.00	CM *374.80 FL	✓
15	1		*License lamp	25.00	0.00	CM *172.20 FL	✓
16	1		*Rear end panel	25.00	0.00	CM *636.20 FL	✓
17	1		*Rear end panel top garnish	25.00	0.00	CM *165.00 FL	✓
18	1		*Rear LH fender innertrim	25.00	0.00	CM *475.40 FL	✓
19	1		*Rear RH fender innertrim	25.00	0.00	CM *475.40 FL	✓
20	1		*Trunk floor panel	25.00	0.00	CM *845.40 FL	X
21	1		*Trunk floor trim	25.00	0.00	CM *301.50 FL	X
22	1		*Tailgate inner trim	25.00	0.00	CM *399.20 FL	✓

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 11,566.20
 - List Item Discount on L Items (S\$) 2,891.55
 Total Parts (S\$) 8,674.65

City Auto Pte Ltd/SNK3640J/12/06/2023 10:36. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Glass sealant	40.00
2	1	Number plate	20.00
3	1	Number plate casing	25.00
4	1	Rear view camera	450.00
5	2	Reverse sensor	700.00
6	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			1,246.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	- To remove and refit rear windscreen glass	New	150.00
2	- To remove and refit rear trims and upholstery	New	120.00
3	- To supply panel sealant and to seal off all weld spot seam and gaps	New	90.00
4	- To install rear view camera and reverse sensor	New	80.00
5	- To spray rubberized under coating	New	120.00
6	- To knock jackout damaged parts, panel beating, welding , align, refix and to renew accident parts	New	900.00
7	- Spary painting on affected and replace parts	New	1,200.00
Gross Labour Cost (\$\$)			2,660.00

City Auto Pte Ltd/SNK3640J/12/06/2023 10:36. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >