

ASS. REC. BY:

REF:

TJ / 23005935/KP

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHB9881D

Yr Regn:

10, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Prius

c.c

1798

Colour

M.P. White/Red

A/C:

Insured / Std / NI / NA

Sp.Reading

188829

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

J7DKB31FU 803092374

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Greenlander

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

27/5/23

D.O.I.

12/6/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S PM body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/6 @ 2164.36 Carhu

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Parks

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Not Authored

\$ 2164.36

Trans-cab Auto Services Pte Ltd

AAD2305-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9981D

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHB9981D

JTDKB3FU803092374

200303878K

TOYOTA

PRIUS GEN 4

27/05/2023

SLV966E / III

23/10/2020

PART

LIST

1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	1,641.36	
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	243.81	
1	HANDLE ASSY, FRONT DOOR OUTSIDE, LH	\$	493.40	
1	WEATHERSTRIP, FRONT DOOR, LH	\$	292.32	
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	139.86	
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	123.06	
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	16.91	
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	55.02	
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	33.29	
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	1,161.83	
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	300.62	
1	MIRROR ASSY, OUTER REAR VIEW, LH	\$	1,695.65	
1	FENDER SUB-ASSY, FRONT LH	\$	1,236.69	
1	LINER, FRONT FENDER, LH	\$	265.55	X
1	EMBLEM, SIDE PANEL	\$	68.88	
1	RIM	\$	1,995.11	X
1	CAP, WHEEL	\$	266.91	
1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	624.54	X

TOTAL \$ 10,654.81
25% \$ 2,663.70
\$ 7,991.11

Special Nett

1SET	DOOR TRIM CLIP	\$	70.00	X
1SET	DOOR WEATHERSTRIP CLIP	\$	65.00	X

Trans-cab Auto Services Pte Ltd

AAD2305-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9981D

- 1 DOOR STICKER TRANSCAB
- 1SET CLIP, ROCKER PANEL MOULDING
- 1SET BUMPER CLIP FRT
- 1SET FRNT BUMPER RETAINER CLIP
- 1SET FENDER CLIP
- 1 FENDER LINER CLIP

\$	<i>na</i>	100.00	<i>60\$ —</i>
\$	<i>na</i>	65.00	X
\$	<i>na</i>	65.00	X
\$	<i>na</i>	85.00	X
\$	<i>na</i>	130.00	X
\$	<i>na</i>	65.00	X
TOTAL		\$ 645.00	
TOTAL PARTS		\$ 2,300.00	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	<i>30\$</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>30\$</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>na</i> 380.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>50\$</i>
To reinstall rear bumper parking sensor.	\$	<i>na</i> 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	<i>20\$</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>15\$</i>
To check steering geometry and computer wheel alignment	\$	220.00	<i>60\$</i>

Trans-cab Auto Services Pte Ltd

AAD2305-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9981D

To remove and refit of rear fender fittings, attachment and
perform water seepage test.

	\$	<i>170.00</i>	X
TOTAL	\$	5,100.00	
Over All Total	\$	15,391.11	

(PART-BY-PART) Repair Days*05 Days**2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: