ASSIGN	MENT
--------	------

From: Date:	Veh No: SLP954X Yr Regn: 2017 1 MAY
Estimated Cost:	Type; M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SLP 954 X	Make: MAZDA 3 SEONU 15 ATS/R C.C 1496
at Workshop m/s PG LANSW)	Colour BUTUK A/C: Insured / Std / NI / NA
of 74, Kim nex	Sp.Reading 3846/4 T/Radio: Insured / Std / NI / NA
Insured: NTMC	Eng/No:
Policy No.	CINO: JM68N22A8HO154361
Claims No.	Gen. Cond: Good / Fair/ Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: (Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nit / S/Rim / STD A/Rim or
	Tyre Size: F: 205/60 R16
(Policy Condition)	R:
Remark: The veh had commenced its N/S 0/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO OF WESTLYKE
Bal. or Market Value: 57K	Front / Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 68/06/23 D.O.I. (2/06/23
Lum Sum: % 3 Val.: Yes or No	Survey held at PEGASUS
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S/I N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
REPAIR LIMIT - 30K	
Danis Sources Un to 440	, 8 days Wed \$ 11115.60, 77)
with Therefore of a il	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
52 0 1	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fee	: Site Insp (\$ )S+RS,SI
	: Interview (\$ ) Photos
Report Format :	: Tech. Invs (\$ ) Others
Lump Sum / I.B.1: (\$ 4400)	:Weekend (\$
	TOTAL



# ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO: 201101753C

### Quotation

From:

(

PEGASUS ENGINEERING & TRADING PTE LTD

74 KIAN TECK ROAD SINGAPORE 628800

Officer in Charge: VIVIAN TAN EE WI

Tel:

Email:

Remarks:

Customer:

**GRAB RENTALS PTE LTD** 

3 MEDIA CLOSE #07-03

SINGAPORE 138498

Attn::

Fax No.:

Quotation No.: QO23/06-1071	Quotation Date: 09/06/2023	Terms: 60 DAYS	
Vehicle No.: SLP954X Chassis No.: JM6BN22A8H0154361		Policy Number: A29069766MKF	
Model: MAZDA 3		Date of Accident: 09/06/2023	
Third Party Insurer: NTUC		TP Vehicle No.: SLZ2190S	

3 REAR FENDER (RHS) *** 1 1,578.0000 1,578 4 REAR FENDER INNER SPLASH SHIELD (RHS) *** 1 168.0000 168 5 REAR FENDER INNER SPLASH SHIELD CLIPS @ 6PCS *** 1 168.0000 495 6 REAR FENDER INNER TRIM BOARD (RHS) *** 1 495.0000 495 7 REAR FENDER INNER TRIM BOARD CLIPS @ 7PCS *** 1 218.0000 218 8 REAR DOOR (RHS) *** 1 218.0000 218 9 REAR DOOR LOCK (RHS) *** 1 585.0000 496 885 10 REAR DOOR INNER TRIM BOARD (RHS) *** 1 585.0000 496 885 11 REAR DOOR INNER TRIM BOARD CLIPS @ 10PCS *** 1 585.0000 496 885 12 REAR DOOR HINGE @ 2PCS   pc   law   bf   2 98.0000 198 13 REAR DOOR CHECKER (RHS) *** 2 98.0000 198 14 REAR DOOR OUTER CHROME MOULDING (RHS) *** 1 105.0000 105 15 REAR DOOR CENTER B PILLAR GARNISH (RHS) *** 1 198.0000 198 15 REAR DOOR REGULATOR (RHS) *** 1 198.0000 198 16 REAR DOOR OUTER HANDLE (RHS) *** 1 195.0000 198 17 REAR DOOR OUTER HANDLE (RHS) *** 1 195.0000 198 18 REAR DOOR OUTER HANDLE (RHS) *** 1 195.0000 198 19 REAR DOOR OUTER HANDLE (RHS) *** 1 195.0000 198 10 REAR DOOR WEATHERSTRIP (RHS) *** 1 198.0000 198 11 REAR DOOR WEATHERSTRIP (RHS) *** 1 198.0000 198 12 REAR DOOR WEATHERSTRIP (RHS) *** 1 198.0000 120.70 198 12 REAR DOOR BODY RUBBER SEAL (RHS) *** 1 198.0000 120.70 198 12 REAR DOOR BODY RUBBER SEAL (RHS) *** 1 198.0000 120.70 198 11 REAR DOOR BODY RUBBER SEAL (RHS) *** 1 198.0000 120.70 198	ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
3 REAR FENDER (RHS) *** 1 1,578.0000 1,578 4 REAR FENDER INNER SPLASH SHIELD (RHS) *** 1 168.0000 168 5 REAR FENDER INNER SPLASH SHIELD CLIPS @ 6PCS *** 1 168.0000 495 6 REAR FENDER INNER TRIM BOARD (RHS) *** 1 495.0000 495 7 REAR FENDER INNER TRIM BOARD CLIPS @ 7PCS *** 1 5.0000 35 8 REAR DOOR (RHS) *** 1 218.0000 218 9 REAR DOOR LOCK (RHS) *** 1 585.0000 47 6.80 10 REAR DOOR INNER TRIM BOARD (RHS) *** 1 585.0000 47 6.80 11 REAR DOOR INNER TRIM BOARD CLIPS @ 10PCS *** 1 585.0000 47 6.80 12 REAR DOOR HINGE @ 2PCS   PL Law H 2 98.0000 199 13 REAR DOOR CHECKER (RHS) *** 1 105.0000 105 14 REAR DOOR OUTER CHROME MOULDING (RHS) *** 1 188.0000 188 15 REAR DOOR CENTER B PILLAR GARNISH (RHS) *** 1 198.0000 199 16 REAR DOOR REGULATOR (RHS) *** 1 198.0000 199 17 REAR DOOR REGULATOR MOTOR (RHS) *** 1 198.0000 199 18 REAR DOOR OUTER HANDLE (RHS) *** 1 195.0000 199 18 REAR DOOR OUTER HANDLE (RHS) *** 1 195.0000 199 18 REAR DOOR OUTER HANDLE (RHS) *** 1 195.0000 199 19 REAR DOOR WEATHERSTRIP (RHS) *** 1 198.0000 199 20 REAR DOOR WEATHERSTRIP (RHS) *** 1 198.0000 1000 1000 1000 1000 1000 1000 100	1	REAR BUMPER - REPAINT Xnn	1		
4 REAR FENDER INNER SPLASH SHIELD (RHS)	2	REAR BUMPER CLIPS @ 10PCS X	10	4.0000	40.00
4 REAR FENDER INNER SPLASH SHIELD (RHS) \\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	3	REAR FENDER (RHS) raphy	1	1,578.0000	1,578.00
5 REAR FENDER INNER SPLASH SHIELD CLIPS @ 6PCS \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	4		1	168.0000	168.00
6 REAR FENDER INNER TRIM BOARD (RHS) ★ ↑ 1 495.0000 495 7 REAR FENDER INNER TRIM BOARD CLIPS @ 7PCS ★ ↑ ↑ 5.0000 35 8 REAR DOOR (RHS) ★ ↑ ↑ 1,250.0000 1 1,250 9 REAR DOOR LOCK (RHS) ★ ↑ ↑ 1 218.0000 1 1,250 10 REAR DOOR INNER TRIM BOARD (RHS) ? ↑ ↑ 1 585.0000 49 € ₹ 10 585.0000 1 1,250 11 REAR DOOR INNER TRIM BOARD CLIPS @ 10PCS ↑ ↑ 1 105.0000 1 1,550 12 REAR DOOR HINGE @ 2PCS   pc   bo	5	REAR FENDER INNER SPLASH SHIELD CLIPS @ 6PCS **	6	5.5000	33.00×
7 REAR FENDER INNER TRIM BOARD CLIPS @ 7PCS	6		1	495.0000	495.00
8 REAR DOOR (RHS)	7		7	5.0000	35.00 ×
9 REAR DOOR LOCK (RHS)	8		1	1,250.0000	1,250.00
10 REAR DOOR INNER TRIM BOARD (RHS) ?	9		1	218.0000	218.00 7
11 REAR DOOR INNER TRIM BOARD CLIPS @ 10PCS	10	0 /	1	585.0000	496.80-585.00
12 REAR DOOR HINGE @ 2PCS   pc Lond   198,0000   198  13 REAR DOOR CHECKER (RHS)   7.	11		10	5.5000	55.00
1 105.0000 105 14 REAR DOOR OUTER CHROME MOULDING (RHS) ?	12	REAR DOOR HINGE @ 2PCS (pc Long H)	2	98.0000	196.009
14 REAR DOOR OUTER CHROME MOULDING (RHS)	13	REAR DOOR CHECKER (RHS) 7. XAA	1	105.0000	105.00 ×
15 REAR DOOR CENTER B PILLAR GARNISH (RHS)	14	REAR DOOR OUTER CHROME MOULDING (RHS) ?	1	188.0000	188.00×
1 198.0000 198 17 REAR DOOR REGULATOR MOTOR (RHS)	15		1	155.0000	155.00
17 REAR DOOR REGULATOR MOTOR (RHS)	16		1	198.0000	198.00 >
18 REAR DOOR OUTER HANDLE (RHS)			1	195.0000	195.00
19 REAR DOOR OUTER HANDLE CAP (RHS) 1 45.0000 45 20 REAR DOOR WEATHERSTRIP (RHS) 1 198.0000 120.70 198 21 REAR DOOR BODY RUBBER SEAL (RHS) 1 212.0000 212		REAR DOOR OUTER HANDLE (RHS) 🗸 🔨	1	177.0000	177.00
20 REAR DOOR WEATHERSTRIP (RHS) 1 198.0000 120.70 198 21 REAR DOOR BODY RUBBER SEAL (RHS) 2 1 212.0000 212		REAR DOOR OUTER HANDLE CAP (RHS)	1	45.0000	45.00
21 REAR DOOR BODY RUBBER SEAL (RHS) $4 \times 1$ 212.0000 212			1	198.0000	120.70 198.00
		REAR DOOR BODY RUBBER SEAL (RHS) 4×1~	1	212.0000	212.00
			1	1,345.0000	1228.97,345.00

C/F 0.00

Page 1 of 3



## **ENGINEERING & TRADING PTE LTD**

GST / ROC COMPANY NO: 201101753C

### Quotation

From:

PEGASUS ENGINEERING & TRADING PTE LTD

74 KIAN TECK ROAD SINGAPORE 628800

Officer in Charge: VIVIAN TAN EE WI

Tel:

Email:

Customer:

GRAB RENTALS PTE LTD

3 MEDIA CLOSE #07-03

SINGAPORE 138498

Attn:: Tel:

Fax No.:

Quotation No.: QO23/06-1071	Quotation Date: 09/06/2023	Terms: 60 DAYS
Vehicle No. : SLP954X	Chassis No.: JM6BN22A8H0154361	Policy Number : A29069766MKF
Model: MAZDA 3		Date of Accident: 09/06/2023
Third Party Insurer : NTUC		TP Vehicle No.: SLZ2190S

23 FRONT DOOR LOCK (RHS)	ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
24 FRONT DOOR INNER TRIM BOARD (RHS)		7~0			
25 FRONT DOOR INNER TRIM BOARD CLIPS @ 10PCS		FRONT DOOR LOCK (RHS)	1		218.00
26 FRONT DOOR OUTER CHROME MOULDING (RHS) 7	24		1	695.0000	695.00×
27 FRONT DOOR CENTER B PILLAR GARNISH (RHS)	25		10	5.5000	55.00
28 FRONT DOOR OUTER HANDLE (RHS)	26	FRONT DOOR OUTER CHROME MOULDING (RHS) 7. XXX	1	199.0000	199.00 🗡
29 FRONT DOOR OUTER HANDLE CAP (RHS) 74 1 45.0000 45.0 30 FRONT DOOR REGULATOR (RHS) ? **X^*** 31 FRONT DOOR REGULATOR MOTOR (RHS) **X^** 32 FRONT DOOR SWITCH (RHS) **X^** 33 FRONT DOOR WEATHERSTRIP (RHS) **X^** 34 FRONT DOOR BODY RUBBER SEAL (RHS) ? **X^** 35 FRONT DOOR CATCH (RHS) **X^** 36 SIDE MIRROR (RHS) **X^** 37 CENTER B-PILLAR PANEL (RHS) **X^** 38 ROCKER PANEL (RHS) **X^** 40 REAR WINDSCREEN GLASS MOULDING **X^** 41 198.0000 198.0 42 REAR WHEEL HUP CAP (LHS) **X^** 41 120.0000 120.0	27	FRONT DOOR CENTER B PILLAR GARNISH (RHS) 🍎 📉 🗥	1	158.0000	158.00 🗡
30 FRONT DOOR REGULATOR (RHS) ? X 1 218.0000 218.0 31 FRONT DOOR REGULATOR MOTOR (RHS) X 1 198.0000 198.0 32 FRONT DOOR SWITCH (RHS) X 1 285.0000 285.0 33 FRONT DOOR WEATHERSTRIP (RHS) X 1 198.0000 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00 100.00	28	FRONT DOOR OUTER HANDLE (RHS)	1	218.0000	218.00 XA
31 FRONT DOOR REGULATOR MOTOR (RHS) XM  32 FRONT DOOR SWITCH (RHS) XM  33 FRONT DOOR WEATHERSTRIP (RHS) XM  34 FRONT DOOR BODY RUBBER SEAL (RHS) 7 XM  35 FRONT DOOR CATCH (RHS) XM  36 SIDE MIRROR (RHS) XM  37 CENTER B-PILLAR PANEL (RHS) YM  38 ROCKER PANEL (RHS) YM  40 REAR WINDSCREEN GLASS MOULDING XM  41 LESS 20%  42 REAR WHEEL HUP CAP (LHS) XM  1 198.0000  198.0  1 198.0000  198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0  1 198.0000  1 198.0000  1 198.0000  1 198.0000  1 198.0000  1 198.0000  1 198.0000  1	29	FRONT DOOR OUTER HANDLE CAP (RHS)	1	45.0000	45.00
32 FRONT DOOR SWITCH (RHS)	30	FRONT DOOR REGULATOR (RHS) ? XAA	1	218.0000	218.00×
33 FRONT DOOR WEATHERSTRIP (RHS)	31	FRONT DOOR REGULATOR MOTOR (RHS) XM 4252'	39 <sub>1</sub>	198.0000	198.00
34 FRONT DOOR BODY RUBBER SEAL (RHS) 7 1 212.0000 212.0 35 FRONT DOOR CATCH (RHS)	32	FRONT DOOR SWITCH (RHS) XNA	1	285.0000	285.00×
35 FRONT DOOR CATCH (RHS) X^1  36 SIDE MIRROR (RHS) X 1  498.0000 498.0  37 CENTER B-PILLAR PANEL (RHS) Y 1  38 ROCKER PANEL (RHS) Y 1  40 REAR WINDSCREEN GLASS MOULDING X 1  40 REAR WHEEL HUP CAP (LHS) X 1  41 LESS 20% 1  42 REAR WHEEL HUP CAP (LHS) X 1  1 120.0000 120.00	33	FRONT DOOR WEATHERSTRIP (RHS)	1	198.0000	110.92 198.00
36 SIDE MIRROR (RHS)	34	FRONT DOOR BODY RUBBER SEAL (RHS) 7 11 3401	1	212.0000	212.00 🗡
37 CENTER B-PILLAR PANEL (RHS)	35	FRONT DOOR CATCH (RHS) X^1	1	65.0000	65.00 ×
38 ROCKER PANEL (RHS)	36	SIDE MIRROR (RHS) 🔀 🔨	1	498.0000	498.00 🗡
39 FRONT FENDER (LHS) - REPAINT	37	CENTER B-PILLAR PANEL (RHS)	1	1,078.0000	1,078.00XR
40 REAR WINDSCREEN GLASS MOULDING \( \sqrt{1} \) 41 LESS 20% 42 REAR WHEEL HUP CAP (LHS) \( \sqrt{1} \) 41 120.0000 198.0 1 120.0000 120.00	38	ROCKER PANEL (RHS)	1	1,648.0000	587 1,648.00
41 LESS 20% 1 -2,731.4000 -2,731.4 42 REAR WHEEL HUP CAP (LHS)   1 120.0000 120.00	39	FRONT FENDER (LHS) - REPAINT X	1		X
42 REAR WHEEL HUP CAP (LHS) X 1 120.0000 120.0	40	REAR WINDSCREEN GLASS MOULDING	1	198.0000	198.00 X
	41	LESS 20%	1	-2,731.4000	-2,731.40
43 REAR WINDSCREEN GLASS SEALANT \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	42	REAR WHEEL HUP CAP (LHS) X	1	120.0000	120.00 🗡
111	43	REAR WINDSCREEN GLASS SEALANT	1	80.0000	80.00
44 TO REMOVE & REFIX BACK REAR WINDSCREEN GLASS. 1 200.0000 200.0	44	TO REMOVE & REFIX BACK REAR WINDSCREEN GLASS.	1	200.0000	200.00 🗶



### **ENGINEERING & TRADING PTE LTD**

GST / ROC COMPANY NO: 201101753C

#### Quotation

From:

**PEGASUS ENGINEERING & TRADING PTE LTD** 

74 KIAN TECK ROAD SINGAPORE 628800

Officer in Charge: VIVIAN TAN EE WI

Tel: Email: Customer:

GRAB RENTALS PTE LTD

3 MEDIA CLOSE #07-03 SINGAPORE 138498

Attn:: Tel:

Fax No.:

Quotation No.: QO23/06-1071	Quotation Date: 09/06/2023	Terms: 60 DAYS
Vehicle No. : SLP954X	Chassis No.: JM6BN22A8H0154361	Policy Number: A29069766MKF
Model: MAZDA 3	3	Date of Accident: 09/06/2023
Third Party Insurer: NTUC		TP Vehicle No.: SLZ2190S
Remarks :		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUN	NT (SGD)
45	TO REMOVE & REARRANGE ELECTRICAL WIRING SYSTEM FOR FACILITATE REPAIR.	1	120.0000	B/F 40	0.00 120.00
46	TO REMOVE & TRANSFER RHS FRONT & REAR DOOR MECHANISM TO THE NEW DOOR.	1	200.0000	120	200.00
47	TO REMOVE & REFIX BACK INNER TRIMMINGS, GARNISHES, SEATS AND RPOOF LINING FOR FACILITATE REPAIR.	1	150.0000	80	150.00
48	TO APPLY RUSTPROOFING & TUFFCOATING TREATMENT FOR THE REPLACED PARTS.	1	120.0000	60	120.00
49	TO KNOCKING & PANEL BEATING.	1	2,000.0000	800	2,000.00
50	TO PUTTY & SPRAY PAINT ON THE AFFECTED AREAS.	1	1,600.0000	1000	1,600.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

ate:

210000 5501.910 269.52 4401.52 49-84400

2/06/23 P(145

 Sub Total
 15,515.60

 GST(8.00%)
 1,241.25

 Total (SGD)
 16,756.85

SJ0G2369000Z / JP Knights Pte Ltd ENTRY DATE & TIME: 09/06/2023 15:32 (SGT) SUBMITTED BY: Weine Chieng VERSION: 1 (09/06/2023 15:32 (SGT))

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission 09/06/2023 15:32 (SGT) Reported by Actual Driver Date of Accident 09/06/2023 12:30 (SGT) Exact Location of Accident Amber Rd, Singapore Additional Location Information Country/State of Loss Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SLP954X

#### INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner GRAB RENTALS PTE LTD Company Reg No 2XXXXX200G Email Address gr.sg.accident@grab.com Mobile Phone No (Phone) +65-91169988 Alternative Phone No (Office) +65-66550005

#### VEHICLE PARTICULARS

Manufacturer Mazda Model 3 Variant Exact purpose for which vehicle was being used at time of Private hire Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private hire Transmission Auto 1496

#### **INSURANCE COMPANY**

Name of Insurance Company India International Insurance Pte Ltd Policy Number / Cover Note Number D21MFL0000447 02

#### DRIVER

Name of Driver TAN KOK TONG NRIC No SXXXX836A Date Of Birth 30/07/1965 Occupation Outdoor

Date Of Driving Pass 31/07/2015 Driving experience 7 YEARS AND 11 MONTHS Gender Mobile Number (Phone) +65-91169988 Alt. Phone Number Email Address gr.sg.accident@grab.com Address BLK 86 LORONG 2 TOA PAYOH #10-343 Address complement Postcode 310086 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Cross Junction Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement **DETAILS OF POLICE ACTION** Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT ON 09/06/2023 AT ABOUT 1230HRS I WAS DRIVING VEHICLE A (SLP954X) ALONG AMBER ROAD. WHILE DRIVING STRAIGHT NEAR TO 30 AMBER ROAD, VEHICLE B (SLZ2190S) SUDDENLY MAKE A TURN AND COLLIDED ONTO VEHICLE A. NOBODY WAS INJURED DURING THE ACCIDENT. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SLZ2190S Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category

Private car

Name of Driver	YAP CHOON LYE
NRIC No	SXXXX927H
Contact Number	=
Address	-
Address complement	II.
Postcode	2
Insurance Company Name	2
Nature Of Damage	
Details of property damaged in accident	(a)
No. Of Passenger (Including Driver)	-

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please correctly report the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers" lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims.
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (b) administering my claims (including the mailing of correspondence, statements, invoices, reports, or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(Collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (e) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



FLASH ACCIDENT
REPORTING OFFICER
FRO NAZREEN

Policyholder's Signature / Date & Time Driver's Signature (If driver is not the policyholder) / Date& Time 09/06/2023 1455HRS Witnessed by Reporting CentrePersonnel

#### Sketch Plan



#### Describe Circumstances of the Accident

ON 09/06/2023 AT ABOUT 1230HRS I WAS DRIVING VEHICLE A (SLP954X) ALONG AMBER ROAD. WHILE DRIVING STRAIGHT NEAR TO 30 AMBER ROAD, VEHICLE B (SLZ2190S) SUDDENLY MAKE A TURN AND COLLIDED ONTO VEHICLE A. NOBODY WAS INJURED DURING THE ACCIDENT.

#### Declaration

I/We declare the foregoing particulars are true in every respect.



FLASH ACCIDENT
REPORTING OFFICER
FRO NAZREEN

Policyholder's Signature / Date & Time Driver's Signature (If driver is not the policyholder) / Date& Time

09/06/2023 1455HRS

Witnessed by Reporting CentrePersonnel