

**SERVICE ESTIMATE**

##### - C00001      SL: SERVICE SALES - PC  
 Mr Terry Tan Soon Lee @huiiri Amita  
 27 Olive Road

Singapore 298264

Closed by .... : Richmond Ho  
 Svc Consultant :  
 Remarks ..... : Mr Terry Tan Soon Le

GST Reg.No:M28920628X  
 Inv.No. . : B&P            0 Page 1  
 Inv.date. : 06/06/2023  
 WIP No. . : 22671  
 Veh.In/Out: 05/06/2023  
 \*Tel.No. . : Mobile: 98421589  
 Reg.No. . : SMN2639S  
 Reg.date . : 30/07/2019  
 Mileage .. : 0  
 Chassis No: YV1ZW10ACL1347073

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRT BUMPER,FRT LH FENDER, FRT LH DOOR,REAR LH DOOR,REAR LH FENDER,REAR BUMPER,ETC	0	8500.00	0		8,500.00 S	7650/
800	TO PUTTY SPRAY PAINT ON FRT BONNET,FRT BUMPER,FRT LH FENDER,FRT LH PILLAR,FRT LH DOOR,REAR LH DOOR,REAR LH FENDER,REAR BUMPER,ETC	0	7500.00	0		7,500.00 S	7225/
802	TO TRANSFER FRONT LH & REAR LH DOOR PARTS	0	500.00	0		500.00 S	/
802	TO REMOVE & INSTALL INTERIOR P	0	1700.00	0		1,700.00 S	/
802	TO REMOVE & INSTALL REAR BOOT COMPARTMENT PARTS	0	850.00	0		850.00 S	/
89994	TO INSTALL REAR LH QUARTER GLASS FILM	0	280.00	0		280.00 S	/
031	TO REPLACE FRONT LH RIM	0	50.00	0		50.00 S	/

### SERVICE ESTIMATE

##### - C00001 SL: SERVICE SALES - PC  
 Mr Terry Tan Soon Lee @huiri Amita  
 27 Olive Road

Singapore 298264

Closed by .... : Richmond Ho  
 Svc Consultant :  
 Remarks ..... : Mr Terry Tan Soon Le

GST Reg.No:M28920628X  
 Inv.No. . . : B&P 0 Page 2  
 Inv.date. : 06/06/2023  
 WIP No. . . : 22671  
 Veh.In/Out: 05/06/2023  
 \*Tel.No. . . : Mobile: 98421589  
 Reg.No. . . : SMN2639S  
 Reg.date . : 30/07/2019  
 Mileage ... : 0  
 Chassis No: YV1ZW10ACL1347073

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
10	COMPUTERISED WHEEL ALIGMENT	0	280.00	0		280.00	S
280	TO CHECK WIRING INCLUDE	0	570.00	0		570.00	S
	RESETTING OF ALL ELECTRICAL						
	MODULES						
R16	TOWING CHARGES (convert?)	0	250.00	0		250.00	S
	BUMPER COVER FRT RD <i>turn</i>	1.0 EA	2487.40			2,487.40	S 2238.66
	V032132220/RADIATOR <i>XAN</i>	1.0 EA	991.20			991.20	S X
	BUMPER BRACKET FRT L <i>turn</i>	1.0 EA	95.50			95.50	S 85.95
	BUMPER BRACKET FRT R <i>XAN</i>	1.0 EA	95.50			95.50	S X
	BUMPER CLIP GREEN S6 <i>nee</i>	10.0 EA	6.00			60.00	S 54.00
	BUMPER BRACKET FRT L <i>turn</i>	1.0 EA	95.50			95.50	S 85.95
	BUMPER BRACKET FRT R <i>XAN</i>	1.0 EA	95.50			95.50	S X
	BUMPER FOAM ALL SV60 <i>XAN</i>	1.0 EA	143.20			143.20	S X
	BUMPER BRACKET FRT A <i>turn</i>	3.0 EA	71.10			213.30	S 191.97
	BUMPER UNDER TRAY S6 <i>XAN</i>	1.0 EA	215.70			215.70	S X
	BUMPER GUIDE SV60 2 <i>XAN</i>	2.0 EA	45.70			91.40	S X
	BUMPER CLIP S80 07- <i>nee</i>	10.0 EA	6.00			60.00	S 54.00

### SERVICE ESTIMATE

##### - C00001 SL: SERVICE SALES - PC  
 Mr Terry Tan Soon Lee @huiri Amita  
 27 Olive Road

Singapore 298264

Closed by .... : Richmond Ho  
 Svc Consultant :  
 Remarks ..... : Mr Terry Tan Soon Le

GST Reg.No:M28920628X  
 Inv.No. . : B&P 0 Page 3  
 Inv.date. : 06/06/2023  
 WIP No. . : 22671  
 Veh.In/Out: 05/06/2023  
 \*Tel.No. . : Mobile: 98421589  
 Reg.No. . : SMN2639S  
 Reg.date . : 30/07/2019  
 Mileage .. : 0  
 Chassis No: YV1ZW10ACL1347073

Op.No	Description	Mech Qty	Price Disc%	Pkg	Amount	G
	MESH GRILLE LH RD SV <i>XSM/</i>	1.0 EA	269.60 ✓		269.60 S	242.64
	MESH GRILLE RH RD SV <i>XAN</i>	1.0 EA	269.60		269.60 S	
	MESH BRACKET LH RD S <i>XM</i>	1.0 EA	66.40		66.40 S	
	MESH BRACKET RH RD S <i>XAN</i>	1.0 EA	66.40		66.40 S	
	BUMPER GRILLE LOWER <i>XM</i>	1.0 EA	377.40		377.40 S	
	BUMPER GRILLE SEAL A <i>XAN</i>	1.0 EA	88.90		88.90 S	
	TOW COVER FRT RD B4 <i>XAN</i>	1.0 EA	89.80		89.80 S	
	NUMBER PLATE RETAINE <i>XAN</i>	1.0 EA	78.00		78.00 S	
	V032277114/CROSS MEM <i>XAN</i>	1.0 EA	226.70		226.70 S	
	STAY <i>XAN</i>	1.0 EA	84.70		84.70 S	
	STAY <i>XAN</i>	1.0 EA	84.70		84.70 S	
	BRACKET LH TOP PANEL <i>tan</i>	1.0 EA	75.80 ✓		75.80 S	68.22
	FENDER PANEL FRT LH <i>tan</i>	1.0 EA	1433.00 ✓		1,433.00 S	1289.70
	V031468231/FENDER CA <i>tan</i>	1.0 EA	253.30 ✓		253.30 S	227.97
	FENDER BRACKET FRT L <i>st</i>	1.0 EA	72.60 ✓		72.60 S	65.34
	SPACER FENDER LH S60 <i>n</i>	1.0 EA	26.80 ✓		26.80 S	24.12
	INSULATING MAT FENDE <i>ms</i>	1.0 EA	367.50 ✓		367.50 S	330.75

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC  
 Mr Terry Tan Soon Lee @huiiri Amita  
 27 Olive Road

Singapore 298264

Closed by .... : Richmond Ho  
 Svc Consultant :  
 Remarks ..... : Mr Terry Tan Soon Le

GST Reg.No:M28920628X  
 Inv.No. . : B&P                      0    Page 4  
 Inv.date. : 06/06/2023  
 WIP No. . : 22671  
 Veh.In/Out: 05/06/2023  
 \*Tel.No. . : Mobile: 98421589  
 Reg.No. . : SMN2639S  
 Reg.date . : 30/07/2019  
 Mileage .. :                      0  
 Chassis No: YV1ZW10ACL1347073

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	FOAMBLOCK LH <i>form</i>	1.0 EA	78.00	/		78.00	S 70.20
	WHEEL ARCH LINER LH <i>mes</i>	1.0 EA	280.70	/		280.70	S 252.63
	MUDFLAP LH <i>mes</i>	1.0 EA	62.30	74.70		62.30	S 67.23
	BUMPER CLIP 8x8,5 <i>mes tan</i>	10.0 EA	9.00			90.00	S
	COVER AIR GUIDE <i>Xan</i>	1.0 EA	1099.10			1,099.10	S
	AIR GUIDE OUTER S60 <i>Xan</i>	1.0 EA	367.50			367.50	S
	AIR GUIDE RADIATOR S <i>Xan</i>	1.0 EA	142.60			142.60	S
	HEADLAMP LED LH S60 <i>can</i>	1.0 EA	3456.50	/		3,456.50	S 3110.85
	FOG LAMP LH SV60 20- <i>Xan</i>	1.0 EA	254.60			254.60	S
	MIRROR PANEL LH T5RD <i>mes</i>	1.0 EA	213.90	/		213.90	S 192.51
	DOOR MIRROR LH T5RD <i>mes</i>	1.0 EA	1132.20	/		1,132.20	S 1018.98
	MIRROR GLASS LH S90 <i>mes</i>	1.0 EA	493.60	/		493.60	S 444.24
	MIRROR BACK COVER LH <i>mes</i>	1.0 EA	530.90	/		530.90	S 477.81
	FRONT DOOR PANEL LH <i>form</i>	1.0 EA	2553.70	/		2,553.70	S 2298.33
	TRIM PANEL BLACK FRT <i>mes</i>	1.0 EA	245.50	/		245.50	S 220.95
	A TRIM MOULDING LH S <i>mes</i>	1.0 EA	213.90	/		213.90	S 192.51
	SEAL STRIP DOOR FRT <i>mes</i>	1.0 EA	285.10	/		285.10	S 256.59

### SERVICE ESTIMATE

##### - C00001      SL: SERVICE SALES - PC  
 Mr Terry Tan Soon Lee @huiri Amita  
 27 Olive Road

Singapore 298264

Closed by .... : Richmond Ho  
 Svc Consultant :  
 Remarks ..... : Mr Terry Tan Soon Le

GST Reg.No:M28920628X  
 Inv.No. . : B&P      0 Page 5  
 Inv.date. : 06/06/2023  
 WIP No. . : 22671  
 Veh.In/Out: 05/06/2023  
 \*Tel.No. . : Mobile: 98421589  
 Reg.No. . : SMN2639S  
 Reg.date . : 30/07/2019  
 Mileage .. : 0  
 Chassis No: YV1ZW10ACL1347073

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	S60 20- RD GUIDE MOUL	1.0 EA	285.10	/		285.10	S 256.59
	S60 20- RD TRIM MOUL	1.0 EA	316.30	/		316.30	S 284.67
	HANDLE OUTER LH XC40	1.0 EA	267.30	/		267.30	S 240.57
	ZV0890100070/NOISE D	1.0 EA	625.10	/		625.10	S 562.59
	REAR DOOR PANEL RH V	1.0 EA	2580.60	137.20		2,580.60	S 2463.48
	TRIM PANEL BLACK REA	1.0 EA	281.70	/		281.70	S 253.53
	TRIM PANEL REAR LH	1.0 EA	153.70	/		153.70	S 138.33
	TRIM PANEL REAR LH	1.0 EA	245.00	/		245.00	S 220.50
	V60 20- SEAL STRIP D	1.0 EA	285.10	/		285.10	S 256.59
	GUIDE MOULDING REAR	1.0 EA	285.10	/		285.10	S 256.59
	TRIM MOULDING REAR L	1.0 EA	316.30	/		316.30	S 284.67
	NOISE DEADENING PAD	1.0 EA	625.10	/		625.10	S 562.59
	HINGE REAR LH UPPER	1.0 EA	227.20	/		227.20	S
	HINGE REAR LH LOWER	1.0 EA	227.20	/		227.20	S 204.48
	DOOR STOP REAR ?	1.0 EA	169.30	/		169.30	S
	ROCKER MOULDIND LH S	1.0 EA	730.60	/		730.60	S 657.54
	*D* PAINT PRIMER 30m	1.0 EA	102.70	/		102.70	S 92.43

### SERVICE ESTIMATE

##### - C00001 SL: SERVICE SALES - PC  
 Mr Terry Tan Soon Lee @huiiri Amita  
 27 Olive Road

Singapore 298264

Closed by .... : Richmond Ho  
 Svc Consultant :  
 Remarks ..... : Mr Terry Tan Soon Le

GST Reg.No: M28920628X  
 Inv.No. . : B&P 0 Page 6  
 Inv.date. : 06/06/2023  
 WIP No. . : 22671  
 Veh.In/Out: 05/06/2023  
 \*Tel.No. . : Mobile: 98421589  
 Reg.No. . : SMN2639S  
 Reg.date . : 30/07/2019  
 Mileage ... : 0  
 Chassis No: YV1ZW10ACL1347073

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	ADHESIVE SEALANT <i>m</i>	1.0 EA	204.40	✓		204.40	S 183.96
	RUST OFF SPECIAL NSF <i>m</i>	1.0 EA	63.40	✓		63.40	S 57.06
	ALLOY RIM 18 XC60 19 <i>af</i>	1.0 EA	1363.80	✓		1,363.80	S 1227.42
	FENDER PANEL REAR LH <i>act</i>	1.0 EA	2571.30	✓		2,571.30	S 2314.17
	BODY PANEL SEALANT <i>m</i>	1.0 EA	825.10	✓		825.10	S 742.59
	QTR GLASS LH V60 20- <i>h</i>	1.0 EA	1013.00	84%		1,013.00	S 795.96
	*D* WINDSCREEN SEALA <i>m</i>	1.0 EA	177.90	✓		177.90	S 160.11

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Rasul*  
*Hp 90010068*  
*16 days*  
*12/06/23 @ 1430*  
*EXCEN: TBA*  
*Repeat*  
*Rep before paint*

	Gross Total.	54,497.80	
Labour Total		20,480.00	Net.....
Parts Total		34,017.80	GST @ 8.0%
Package Total		0.00	Total.....
			Paid.....
			Please Pay..
			58,857.60

GST: S=StdRated; O=OutOfScope; Z=ZeroRated; P=PreviousRate