



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914			Ref: CS3/AWA23003948/Rcy3m4-1 Date: 17/07/2023 Code: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 3437T	Veh. Inspected	SLB 7894M	
Policy No.	BVFCB0013962301	Coverage (\$)	0.00	
Claim No.	NSV2300101/SG	Excess (\$)	0.00	
Assign From	STELLA GOH	Assign Date	08/06/2023	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS CL 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104548757	Colour	GREY	
Odometer	152930 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55R16	WEST LAKE	6 mm	
L/H Front Tyre	205/55R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/55R16	WEST LAKE	6 mm	
L/H Rear Tyre	205/55R16	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/04/2023	Inspection Date	18/04/2023	
Survey held at	GOLD AUTOWORKS PTE LTD 48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	