



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC23001055/Tnp3m4-1 Date: 16/06/2023 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SFD 1233X	Veh. Inspected	SLB 9461R	
Policy No.		Coverage (\$)	0.00	
Claim No.	23/23/23/VP05/026905	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	12/06/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAZDA 3	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JM6BM44A8G0341661	Colour	RED	
Odometer	100364 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	PIRELLI	6 mm	
L/H Front Tyre	205/60 R16	PIRELLI	6 mm	
R/H Rear Tyre	205/60 R16	PIRELLI	6 mm	
L/H Rear Tyre	205/60 R16	PIRELLI	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	30/01/2023	Inspection Date	01/02/2023	
Survey held at	60 JALAN LAM HUAT, #02-20 CARROS CENTRE, S 737869			
Repairer	KIM MOTORING			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	