

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/21P23005971/UV23

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 6BJ7070A

at Workshop m/s 14's BOD

of

Insured: YP531D

Policy No.

Claims No. IVS23/1075

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$72k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

174517396

Date / Time Action / Instruction Sep 12k.

7/7/23 4/587000 informed Susan (red 6064, 46%)

Veh No: 6BJ7070A Yr Regn: 16/107/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA 316 CD1

Make: mer Benz Sprinter c.c 2143

Colour: white A/C: Insured / Std / NI / NA

Sp.Reading: 139038 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDB9061312N732305

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/65R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 Yoko mm

D.O.A. 08/06/23 D.O.I. 12/06/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 8

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2) 7/7/23-typist

Add Fee: ☐ : Site Insp (\$) S + RS, SI

☐ : Interview (\$) Photos

☐ : Tech. Invs (\$) Others

☐ : Weekend (\$)

Report Format : TP

Lump Sum H.B.t: (\$ 7000)

Survey Fee:

Transportation:

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	196N
Vehicle Details	
Vehicle No.:	GBJ7070A
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Jun 2023
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	SPRINTER 316CDI 3250 4X2
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	65195534276924
Chassis No.:	WDB9061312N732305
Maximum Power Output:	-
Open Market Value:	\$45,711.00
Original Registration Date:	16 Jul 2019
First Registration Date:	16 Jul 2019
Transfer Count:	1
Actual ARF Paid:	\$2,286.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Jul 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$28,559.00
COE Rebate Amount:	\$17,396.00
Total Rebate Amount:	\$17,396.00

The information contained herein is correct as at 12 Jun 2023

OK

**Lin's Brother Auto Engineering Workshop**

No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J

liusbro@gmail.com

Tel: 67411730

ESTIMATE

Name: Liberty Insurance Pte Ltd
 Address Motor Claims Department
 51 Club Street #03-00
 Liberty House

Singapore 069428

Ref Date:

09-06-2023

Ref No:

GBJ7070A

Vehicle No:

GBJ7070A230608

Model / Make:

Mercedes Benz Sprinter

Capacity

316CDI 3250 4X2

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear Lh	Side Mirror <i>P-1885</i>	\$ 2,964.00	1	\$ 2,964.00		CNR ✓
2		Freezer Box Panel "Front"	\$ 2,200.00	1	\$ 2,200.00	SN	CNR 1800 <i>S/N</i>
3		Freezer Box Panel "Side"	\$ 1,600.00	1	\$ 1,600.00	SN	CNR ✓ <i>S/N</i>
4		Corner Cab Top & Lower	\$ 300.00	2	\$ 600.00	SN	Dis lower <i>1/2 C S/N</i>
5		Panel Corner	\$ 1,400.00	1	\$ 1,400.00	SN	CNR 800 <i>S/N</i>
6		Panel Corner Lower	\$ 650.00	1	\$ 650.00	SN	MS X
7		Remove and refix rear Freezer Box components & mechanism to facilitates for repair annd Labor Charge	<i>102</i>		\$ 2,500.00		2000
		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 250.00		
		To putty & spray painting & including touch up paint on accident affected areas			\$ 900.00		600
		To apply Rust Proofing , reseal tuff-coating treatment on accident area					

Total Parts & Labour of estimate for damaged vehicle

\$ 13,064.00

Total amount in Lumpsum Basis for repaired vehicle

\$ -

SDL

not Authorised
12/6/23
2/5 \$ 7000
8 days.
take photo after 1 day

Liu's Bro Auto Engrg Wks

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1885
102
P-7696-50
S.N 4500
L-2600
\$796.50
202
7037.