



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23005971/Uvp3m4 Date: 11/07/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 531D	Veh. Inspected	GBJ 7070A	
Policy No.		Coverage (\$)	0.00	
Claim No.	IVS23/1075	Excess (\$)	0.00	
Assign From	ANDY SEAH	Assign Date	12/06/2023	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ SPRINTER 316CDI (A)	c.c	2143	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	WDB9061312N732305	Colour	WHITE	
Odometer	139038 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/65 R16	CONTINENTAL	6 mm	
L/H Front Tyre	235/65 R16	CONTINENTAL	6 mm	
R/H Rear Tyre	235/65 R16	CONTINENTAL	6 mm	
L/H Rear Tyre	235/65 R16	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/06/2023	Inspection Date	12/06/2023	
Survey held at	LIU'S BROTHER AUTO WORK SHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTO BAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)REGISTRATION DATE: 16 JUL 2019 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	