

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA9228B
MAKE HYUNDAI
MODEL I40

DATE: 12.06.23
MVA JUMANI
DOA: 08.06.23

2/sum
ECICS

Qty	Parts Description/ Labour	Type	Unit Price	Amount
10	HEADLAMP LH			\$1,388.00 <i>un.</i>
1	FRT FENDER LH			\$663.00 <i>pt</i>
1	FRT BUMPER ASSY			\$1,025.20 <i>de</i>
1	FRT BUMPER CLIPS			\$22.00 <i>un</i>
1	FRT BUMPER SIDE BRACKET LH			\$44.80 <i>de</i>
			1754.70	
	SUB TOTAL			\$3,143.00
	LESS 20%		1423.76	\$628.60
	DISCOUNTED TOTAL			\$2,514.40
	FRT DOOR COMFORT LOGO			<i>un</i> \$75.00 NET
			75	
	SUB TOTAL			\$75.00 NET
	Labour Charge			
	PANEL BEATING		1305	575 \$900.00
	SPRAY PAINT			750 \$800.00
	TUFF KOTE			30 \$50.00
	CHECK WIRING			<i>un</i> \$50.00
			2783.76	
	TOTAL LABOUR		41512250	\$1,800.00
	ESTIMATE TOTAL		2 days	\$4,389.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Sanjiv 97445749
'un' 12/12/23 @ 5pm
LLS Rising after repair
Sanjiv 2 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: