

ASS. REC. BY: Taufik

REF:

NS/ /W C 23005973/Tvp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: YQ 5585K

Policy No. _____

Claims No. MT/1227437-002


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seer _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Jumani

Vehicle: IN / OUT

Veh No: SHD 6649ZYr Regn: 2020, SepType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Priusc.c. 1798Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading 564338

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SHD 3 FY 70309/555Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: 1.8 / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Weslake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 12/6/2023D.O.I. 12/6/23Survey held at Comfort AgencyDes. of Damages: Frt / Rear / O/S (N/S) / U/G / Rooftop or

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
20/6/23	Lump Sum \$4750 confirmed with Jumani (red 1864.31, 28%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 20/6/23-typist

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format: TP

Lump Sum / L.T. / (\$4750)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

VEHICLE NO SHD6649Z

MAKE : TOYOTA

MODEL : PRIUS

DOA 12.06.123

INS. INCOME

MVA JUMANI

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
FRT BUMPER	1		\$ <i>del</i> 586.18
FRT BUMPER CLIPS	10		\$ <i>ner</i> 22.00
FRT FENDER LH	1		\$ <i>del</i> 1,111.93
FRT FENDER EMBLEM LH	1		\$ <i>ner</i> 86.50
HEADLAMP ASSY LH	1		\$ <i>X</i> 2,637.60
FRT SIDE MIRROR ASSY	1		\$ <i>hms</i> 1,390.10
FRT SIDE MIRROR COVER	1		\$ <i>dis</i> 141.90
FRT BUMPER SIDE BRACKET LH			\$ <i>dis</i> 82.30
SUB TOTAL			\$ 6,058.51
LESS 25%			\$ 1,211.70
DISCOUNTED TOTAL			\$ 4,846.81
 FRT DOOR COMFORT LOGO			\$ <i>ner</i> 75.00
LESS 10%			7.5
SUB TOTAL			\$ 67.50
LABOUR CHARGE			
PANEL BEAT			\$ <i>525</i> 800.00
SPRAYPAINT			\$ <i>250</i> 800.00
CHECK WIRING			\$ <i>250</i> 50.00
TUFF KOTE			\$ <i>30</i> 50.00
<i>Jaylin 02445349</i> <i>WPS 12/6/77 25pm</i> <i>13 hours after repair</i> <i>2-3 days</i> <i>Jaylin Chikentun</i>			
TOTAL LABOUR			\$ 1,700.00
ESTIMATE TOTAL			\$ 6,614.31

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

KKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• This survey is on a "without prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 12.06.2023 15:14

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5899937

JC NO305557419


IS COMFORT TRANSPORTATION PTE LTD OMER NO. 7010045 IESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P)	REGN NO.: SHD6649Z	MILEAGE
	MAKE: TOYOTA	FUEL E.....1/2.....F
	MODEL PRIUS HYBRID(G4A12.	DATE/TIME IN 06.2023 13:05
	YR OF MANU. 30.09.2020	TARGET DATE
	CHASSIS CODE JTDKB3FU703091555	COMPLETION DATE/TIME:

DUNT CARD NO.

JOB DESCRIPTION

Accident Date: 12.06.2023
 ATURE: 3P.12.06.23

'NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

No.: SHD6649Z

JU INCOME

Vehicle No.:

SHD6649Z

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard