

ASS. REC. BY: Taufikh

REF:

NS/INC 23005975/Tvp3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP/WS/TP RES/OD RES/EVA/INV/MV)

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SJK 9707J

Policy No. _____


Claims No. MT/1226929-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: Lim TS

Vehicle: IN / OUT

Veh No: SKD 4770T Yr Regn: 20/9/Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius c.c. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 41444 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDK B3F4 603 090574

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: M / S/Rim / STD A/Rim or

Tyre Size: F: 145/65R15

R: 1 - 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 10/6/2023 D.O.I. 12/6/23

Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
28/6/23	Taufikh confirmed LS \$2750 (Red 6513.84, 70%)

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 28/6/23-typist

Days Of Repair: 3

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Wastelend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Rep. Format: TP

Lump Sum H.B.A. (\$2750)

COMFORTDELGRO ENGINEERING PTE LTD

SAS-KIV

REPAIR ESTIMATE

LKK -

DATE: 12.06.2023

SJK9707J

MODEL: Toyota Prius G4A

INSURANCE: INCOME (45)

MVA: LIM T S

VEHICLE NO.: SHD4770T

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Trunk	1		\$1,303.29 <i>My</i>
	Rear Trunk Outer Garnish	1		\$1,054.71 <i>one</i>
	Rear Trunk Lid Logo (Prius)	1		\$62.14 <i>net</i>
	Rear Trunk Lid Logo (Hybrid)	1		\$62.14 <i>net</i>
	Rear Trunk Lid Logo (Toyota Star)	1		\$81.43 <i>X</i>
	Rear Bumper	1		\$551.89 <i>de</i>
	Rear Bumper Re-Inforcement	1		\$378.32 <i>by</i>
	Rear Bumper Lower Cover-Black	1		\$654.96 <i>de</i>
	Rear Bumper Reflector RH/LH	2	\$55.00	\$110.00 <i>X</i>
	Rear Bumper Side Brkt RH/LH	2	\$112.70	\$225.40 <i>LH de 5 PHX</i>
	Rear Bumper Clips	10	\$2.20	\$22.00 <i>net</i>
	Rear Bumper Tow Cover	1		\$82.70 <i>X</i>
	Rear Trunk Lamp LH	1		\$230.20 <i>X</i>
	TailLamp Upper LH	1		\$557.90 <i>?</i>
	TailLamp Lower LH	1		\$570.00 <i>X</i>
	Rear Bumper Ctr Under Cover	1		\$654.96 <i>X</i>
	Rear Bumper Side Under Cover LH	1		\$232.00 <i>X</i>
	Rear Windscreen Glass	1		\$1,758.70 <i>X</i>
	Rear Windscreen Lower Glass-Black	1		\$805.80 <i>X</i>
	SUB TOTAL			\$9,398.54
	LESS 25%			\$2,349.64
	DISCOUNTED TOTAL			\$7,048.91
	Reverse Sensor	1		\$135.70 <i>net</i>
	Rear Trunk ComfortDelGro	1		\$30.00 <i>net</i>
	Rear Trunk 65521111	1		\$30.00 <i>net</i>
	Rear Trunk ZIG APPS	1		\$40.00 <i>net</i>
	Rear Windscreen Sealant	2	\$46.00	\$92.00 <i>X</i>
	LESS 10%			\$327.70
	S/NETT TOTAL			\$32.77
	TOTAL SPARE PARTS			\$7,343.84
	Labour Charge			
	Panel Beating			\$800.00 <i>525</i>
	Spray Painting Charge			\$600.00 <i>500</i>
	Tuff Kote			\$100.00 <i>X</i>
	Check Lightings			\$60.00 <i>30?</i>
	R/I Rear Windscreen Glasses			\$240.00 <i>X</i>
	Remove/Refix Reverse Sensor			\$120.00 <i>30</i>
	Towing Fee			
	TOTAL LABOUR			\$1,920.00
	ESTIMATE TOTAL			\$9,263.84

This is an initial estimate based on a visual inspection of the above vehicle. The final repair vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are \$9,263.84
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Toyota Prius

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5899877

JC NO305557414


OMER	REGN NO: SHD4770T	MILEAGE
IS COMFORT TRANSPORTATION PTE LTD	MAKE: TOYOTA	FUEL
OMER NO 7010045	MODEL PRIUS HYBRID(G4A10.	E.....1/2.....F
IESS 383 SIN MING DRIVE	YR OF MANU. 20.12.2019	DATE/TIME IN 06.2023 11:00
Singapore SINGAPORE 575717	CHASSIS CODE JTDKB3FU603090574	TARGET DATE
65508755 (R) (O) (P)		COMPLETION DATE/TIME:
JUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 10.06.2023
ATURE: 3P 10.06.2023

DESCRIPTION
LUMPSUM REPAIR-SHD4770T-TP
TOWING FEE

NO LABOR CODE
00010 PB
00020 23-01



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SHD4770T LIMITS

Vehicle No.: SHD4770T

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard

SHD 4770T



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition


1. Date: 10/06/2023 Time Received: 12.15		3. Vehicle Type:	4. Type of Towing:
2. ☐ New ☐ SPARK Kakis Name of Customer : HAMIDI BIN BASAR		☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)	☒ Normal Tow ☐ King Dolly ☐ Flat Bed ☐ Crane-up
Contact No. : 91791415		5. Nature of Service:	6. Parts Replaced/Remarks:
Vehicle No. : STD 4770T			
Make / Model / Colour :			
Email :		☐ Jumpstart ☐ Recovery ☐ Change Tyre / Battery	
7. Location: Tampines AVE 5		8. Vehicle Tow - In Workshop:	
9. Preferred Workshop:		☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi	
☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others:			

10. Odometer Reading : _____

Fuel Level : ☐ F ☐ 1/4 ☐ 1/2 ☐ 3/4 ☐ E

11. Radio / CD Player

☐ OK
☐ Faulty
☐ Not tested



: Cracked X : Dented
/ : Scatched O : Missing

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☐ QA ☐ GAO ☐ OTHERS

Name of Driver : SAM CHEE

Vehicle No. : YQ908614

Time Dispatch : _____

Time of Arrival : _____

Time Completed : _____

Signature of Customer

Cash Invoice Details (if applicable)

13. Cash Invoice No. : _____

Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
- b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
- c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

10/06/2023

Date

12.15

Time

Handwritten signature

Signature of Customer

14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

CUSTOMER'S COPY