

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/A1623005987/Upa3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMH 4255

at Workshop m/s

stytech

of

Insured:

SLA25WE

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

£ 88k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

6866
KTA 829209

Veh No:

SMH 4255

Yr Regn:

22/01/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Merde civic

c.c

1597

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

77218

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRHFC5650JT002314

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55 R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

10/06/23

D.O.I.

13/06/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Day 14k.

16/6/23 4/5 1400 have video in hand w. astor

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

TOTAL

STYTECH AUTO PTE LTD

2 Kaki Bukit Ave 2 #01-03
Kaki Bukit Autohub Singapore 417921
Tel : 64448125 Fax : 64453310
GST Reg .No: 201601539K
Co.Reg: No: 201601539K

not allowed
13/6/23
2/s @ 1400/
3 days
Whaph. Hk 14~

VEHICLE No : SMH 4255J

1PC	FRONT BUMPER	De/To.1	\$579.90	✓
1PC	FRONT BUMPER SIDE RETAINER O/S	11	\$18.40	X
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	grood	\$30.80	✓
1SET	FRONT BUMPER CLIPS	11	\$35.00	✓
1PC	HEADLAMP O/S	scr	\$675.90	✓
1PC	FRONT FENDER O/S	11	\$464.20	X
1PC	FEONT SIGNAL LAMP O/S	scr	\$67.50	✓
			\$1,871.70	
LESS 20%			\$1,497.36	

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	11	\$50.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS		\$400.00 220
TO PUTTY & SPRAY PAINTING		\$650.00 400
TOTAL	\$2,647.36	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7-1388.1
202
1111.28
640
1751.28
203
1001