



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 6577L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT HEADLAMP O/S	CRACKED	2,313.10	786.10
1	FRONT BUMPER	DISTORTED / TORN	1,485.80	655.10
1	FRONT BUMPER FOG LAMP COVER	NOT NECESSARY	86.50	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	412.60	-
1	FRONT BUMPER SIDE RETAINER O/S	CRACKED	49.84	49.84
1	FRONT FENDER - O/S	BENT / DENTED	786.90	786.90
1	FRONT FENDER INNER SHIELD O/S	TORN	155.60	155.60
1	FRONT WASHER TANK	DEFORMED	182.50	182.50
1	FRONT WHEEL BEARING	DAMAGED	126.20	126.20
1	FRONT SHOCK ABSORBER	NOT NECESSARY	408.50	-
1	FRONT KNUCKLE ARM	BENT	406.85	406.85
1	FRONT LOWER ARM	NOT NECESSARY	435.10	-
1	FRONT DRIVE SHAFT - RH	NOT NECESSARY	1,340.95	-
	LESS 25% DISCOUNT		-2,047.61	-787.27
			6,142.83	2,361.82
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	80.00	40.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	60.00	40.00
1	FRONT TYRE (SN)	SERVICEABLE	450.00	-
1	FRONT WHEEL RIM - RH (SN)	WARPED	950.00	450.00
			1,540.00	530.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING.		80.00	20.00
	TO REMOVE AND REFIT FRONT UNDERCARRIAGE.		350.00	120.00
	TO CONDUCT WHEEL ALIGNMENT.		180.00	80.00
	TO APPLY UNDERCOATING.		150.00	30.00
	PANEL BEATING.		1,500.00	400.00

Report Ref No. CS/INC23005992/Uqy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS.		1,400.00	600.00
			3,660.00	1,250.00
GRAND TOTAL			11,342.83	4,141.82
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,300.00

Report Ref No. CS/INC23005992/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.