

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/INL23025992/Ug43

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJK 6577L

at Workshop m/s Boon

of _____

Insured: SMN2143E

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 858k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJK 6577L Yr Regn: 29/10/08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or GA

Make: Toyota wish c.c. 1794

Colour: silver A/C: Insured / Std / NI / NA

Sp.Reading: 183575 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ITDER12W803000880

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front 6 mm Rear 6 mm

R/Bal. 6 mm L/Bal. 6 mm

L/Bal. 6 mm D.O.A. 10/06/23 D.O.I. 13/06/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S L/R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/7/23	Rep/1k.
	coe until 28-10-2028 LPA @ 17345
	4/5 @ 3300 informed EIA (Per @ 804283, 717)

Date/Time, File Pass to?

1) 25/7/23 hupsa

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I: (\$ 3300)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road

#08-1339 Singapore 470130

Tel: 9450 7920

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

zoomautowerks@gmail.com

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

26 June 2023

Acknowledged by Repairer

Signature:

Date:

REG NO.: SJK 6577 L
MAKE/MODEL: TOYOTA WISH

13/06/23

2/s \$3300

4 days

Take the A/R up

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
LIST ITEMS		
1	Front headlamp o/s cna	786.10
1	Front bumper Dis/Torn	655.10
1	Front bumper fog lamp cover	86.50 X
1	Front bumper reinforcement	412.60 X
1	Front bumper side retainer o/s cna	49.84
1	Front fender -RH o/s	786.90
1	Front fender inner shield o/s Torn	155.60
1	Front washer tank	182.50
1	Front wheel bearing	126.20
1	Front shock absorber	408.50 X
1	Front knuckle arm	406.85
1	Front lower arm	435.10 X
1	Front drive shaft -RH	1,340.95 X
		8,190.44
	Less 25%	2,047.61
		6,142.83

SPECIAL NETT ITEMS

1	Front bumper clip (1 set)	80.00 40
1	Front fender inner shield clip (1 set)	60.00 40
1	Front tyre	450.00 X
1	Front wheel rim -RH	950.00 450
		1,540.00

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	80.00 20
2	To remove and refit front undercarriage.	350.00 120
3	To conduct wheel alignment.	180.00 80
4	To apply undercoating.	150.00 30
5	Panel beating.	1,500.00 400
6	To re-spray painting on the affected areas.	1,400.00 600
		3,660.00

GRAND TOTAL :

\$ 11,342.83

2- 3149.09
252
2361.81
530
1250
4141.91
2213