

ASS. REC. BY:

REF:

GAZ 23005999/Kn

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLW 50346 Yr Regn: 02 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra S.c.c 1591

Colour

M.L. Berge

A/C: Insured / Std / NI / NA

Sp. Reading

45265

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM11D 841CM JU 62 8567

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

11/6/23

D.O.I.

14/6/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S & B

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

W/Csp. Said maybe part by part.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLW5034G
TP/GA

M/S : GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE,
16-01 CENTENNIAL TOWER
SINGAPORE 039190

TEL: 68046037

FAX: 62353354

ATTN: Motor Claim Department

Claim No: ES2300616

Estimate No: ES2300616/YISHUN

Date: 14 Jun 2023

Policy No: 5132796612

Veh Reg No: SLW5034G

Make/Model: HYUNDAI HYUNDAI
ELANTRA AD 1.6 GLS
AT (AMS)

WS Ref:

TP/GA

Claim Type:

Third Party

Accident Date:

11/06/2023

TP Veh Reg No:

SMX9447E

Chassis No:

KMHD841CMJU628567

Engine No:

G4FGJU134363

Reg. Date:

19/02/2018

Estimate Repair Cost to Vehicle No : SLW5034G

Pages: 1/2

Description	U/Price	Quantity	Cost S\$	Amount S\$
Cost Plus				
1 REAR BUMPER	280.00	1 PC	280.00	280.00
2 REAR BUMPER REINFORCEMENT	145.00	1 PC	145.00	145.00
3 REAR BUMPER LOWER COVER	105.00	1 PC	105.00	105.00
4 REAR BUMPER LH SIDE RETAINER	25.00	1 PC	25.00	25.00
5 REAR BUMPER LH LAMP	23.00	1 PC	23.00	23.00
6 REAR BUMPER CLIP	2.00	6 PC	12.00	12.00
7 REAR BUMPER RETAINER BRACKETS	10.00	2 PCS	20.00	20.00
8 REAR BOOT	650.00	1 PC	650.00	650.00
9 REAR BOOT INNER LOCK	85.00	1 PC	85.00	85.00
10 REAR BOOT INNER RUBBER	65.00	1 PC	65.00	65.00
11 REAR BOOT INNER TRIM BOARD	105.00	1 PC	105.00	105.00
12 REAR BOOT HINGES	42.00	2 PCS	84.00	84.00
13 REAR BOOT LOGO	22.00	1 PC	22.00	22.00
14 REAR BOOT EMBLEM (ELANTRA)	35.00	1 PC	35.00	35.00
15 REAR BOOT REFLECTORS	160.00	2 PCS	320.00	320.00
16 REAR BOOT NUMBER PLATE LAMPS	30.00	2 PCS	60.00	60.00
17 TAILLAMPS	180.00	2 PCS	360.00	360.00
18 TAILLAMPS SIDE CLIPS	3.00	2 PCS	6.00	6.00
19 REAR END PANEL	170.00	1 PC	170.00	170.00
20 LH TAILLAMP PANEL	100.00	1 PC	100.00	100.00
21 REAR END PANEL INNER TOP GARNISH	38.00	1 PC	38.00	38.00
22 REAR LH FENDER	650.00	1 PC	650.00	650.00
23 REAR LH FENDER INNER GARNISH	120.00	1 PC	120.00	120.00
24 REAR LH FENDER INNER GARNISH CLIPS	2.00	6 PCS	12.00	12.00
25 REAR LH MUD FLAP	35.00	1 PC	35.00	35.00
26 REAR LH UNDER COVER	90.00	1 PC	90.00	90.00
27 REAR SPARE TYRE COMPARTMENT	360.00	1 PC	360.00	360.00
28 REAR SPARE TYRE TOP BOARD	110.00	1 PC	110.00	110.00
29 REAR WINDSCREEN GLASS MOULDING	35.00	1 PC	35.00	35.00
30 REAR TAILLAMP WIRE HARNESS	250.00	1 PC	250.00	250.00
31 FRONT BUMPER	350.00	1 PC	350.00	350.00
32 FRONT BUMPER REINFORCEMENT	195.00	1 PC	195.00	195.00
33 FRONT BUMPER SPONGE	75.00	1 PC	75.00	75.00
34 FRONT BUMPER LH FOG LAMP GARNISH	60.00	1 PC	60.00	60.00
35 FRONT BUMPER LH SIDE RETAINER	20.00	1 PC	20.00	20.00
36 FRONT BUMPER SIDE GARNISHS	32.00	2 PCS	64.00	64.00
37 FRONT BUMPER SIDE GARNISH RIVETS	3.00	8 PCS	24.00	24.00
38 FRONT GRILLE ASSY	290.00	1 PC	290.00	290.00
39 FRONT NUMBER PLATE GARNISH	55.00	1 PC	55.00	55.00
40 LH HEADLAMP	500.00	1 PC	500.00	500.00
41 BONNET	690.00	1 PC	690.00	690.00
			6,695.00	6,695.00
			1,004.25	7,699.25
			Add 15%	

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : GREAT AMERICAN INSURANCE COMPANY
3 TEMASEK AVE,
16-01 CENTENNIAL TOWER
SINGAPORE 039190
TEL: 68046037 FAX: 62353354
ATTN: Motor Claim Department

Claim No: ES2300616
Estimate No: ES2300616/YISHUN
Date: 14 Jun 2023
Policy No: 5132796612
Veh Reg No: SLW5034G
Make/Model: HYUNDAI HYUNDAI
ELANTRA AD 1.6 GLS
AT (AMS)
Chassis No: KMHD841CMJU628567
Engine No: G4FGJU134363
Reg. Date: 19/02/2018

WS Ref: TP/GA
Claim Type: Third Party
Accident Date: 11/06/2023
TP Veh Reg No: SMX9447E

Estimate Repair Cost to Vehicle No : SLW5034G

Pages: 2/2

Description	U/Price	Quantity	Cost S\$	Amount S\$
Special Net				
42 REAR BOOT EMBLEM (S)	20.00	1 PC	20.00	✓
43 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
44 REAR NUMBER PLATE	35.00	1 PC	35.00	✓
45 REAR WINDSCREEN GLASS GUM	40.00	1 UNIT	40.00	✓
46 REVERSE SENSOR	200.00	1 SET	200.00	✓
				330.00
Labour				
47 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
48 REMOVE & REFIX RR BUMPER ASSY,RR BOOT,TAILLAMPS,RR REFLECTORS,CUT,WELD & RENEW RR END PANEL,RR LH FENDER,RR SPARE TYRE COMPARTMENT,STRAIGHTEN,KNOCK & REPAIR RR LH MAIN CHASSISS,RR LH WHEEL HOUSING,RR COMPARTMENT LH EXTENSION PANEL & REALIGN THE SAME	2,500.00	1 LA	2,500.00	?
49 REMOVE & REFIX SEAT,CARPET, TOP ROOF LINING,ETC	100.00	1 LA	100.00	✓
50 PUTTY & RESPRAY PAINT ON REAR COMPARTMENT,REAR LH CHASSIS,BOOT,HINGES,REAR LH FENDER,REAR PANEL,REAR BUMPER,REAR RH FENDER REINFORCEMENT AND REAR AFFECTED AREAS	1,400.00	1 LA	1,400.00	1200
51 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,BONNET,KNOCK & REPAIR FRT SUPPORT PANEL AND REALIGN THE SAME	600.00	1 LA	600.00	400
52 PUTTY & RESPRAY ON FRT BUMPER,FRT SUPPORT PANEL,REINFORCEMENT PANEL,FRT BONNET	600.00	1 LA	600.00	400
53 TO MOUNT ON CAR-O-LINER,JACK & STRAIGHTEN REAR CHASSIS	200.00	1 LA	200.00	?
54 RUSTPROOFING	60.00	1 LA	60.00	✓
				5,560.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total S\$ 13,589.25
Add GST @ 8% 1,087.14
Total Amount payable S\$ 14,676.39

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	12/06/2023 17:44 (SGT)
Reported by	Actual Driver
Date of Accident	11/06/2023 12:05 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	LORONG CHUAN
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLW5034G

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LAI WEIMING
NRIC No	SXXXX234F
Email Address	laiwm1106@yahoo.com
Mobile Phone No	(Phone) +65-90556129
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	ELANTRA AD 1.6 GLS AT (AMS)
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1591

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5132796612

DRIVER

Name of Driver	LAI TIANIAN
NRIC No	SXXXX075C
Date Of Birth	09/08/1994
Occupation	Indoor

Describe Circumstance of the Accident

** NOTE : PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

() Claim Own Policy (☒) Claim Third party () Reporting Only
() Claim OD/ TP at other workshop ()

Sketch Plan

Lorong Chuan	↑	↑	↑	↑	A = SLW5034G
					B = SMX9447E (with 4 passengers)
					Ou Zhi Li
					S 8441752A
					HP - 9698 2860
					C = SMX9341B (Not sure any passenger)
					Long Hong Chuan
					S 7062985B
					HP - 81001191
					D = SLJ278X (Not sure any passenger)
					Heng Sheng Kiat Jaros

T0014208A

HP - 8422 8488

Refer to Police Report No: T/20230611/7020

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card) (Ys)