



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

TP/DS Final

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		Ms Ow Wei Kuen 262C Compassvale Street #05-133 Singapore 543262 Mobile: 91074197		
			Document No. 0				
			Document Date 21/06/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3100068925		2NRX564229	60	Raymond Seah L M	14/06/2023	14.32	--/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:SHB 762D ACC DATE:10/06/2023 TP INS:FIRST CAPITAL NO OF REPAIR DAYS:08 DATE-IN:14/06/2023 DATE SURVEY:14/06/2023 BY:LKK-MARCUS AUTHORISED ON: -TP/DS CLAIM				30.00	
2	S	BP-SUBLET TO SUPPLY AND INSTALL REAR WINDSCREEN 3M SOLAR FILM.	0650			400.00	
3	S	BP-SUBLET SUPPLY SEALANT (NETT) FOR REAR TAILGATE AND REAR END PANEL.	0742			120.00	
4	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			198.00	
5	S	BP-SUBLET TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.	0742			134.64	
6	S	BP-SUBLET R/I REAR WINDSCREEN TO FACILIATE REPAIR.	0742			594.00	
7	S	BP-SUBLET TO TRANSFER REAR TAILGATE BOARD, WIPER MOTOR AND OTHER ATTACHMENT TO FACILIATE REPAIRS.	0742			396.00	
8	S	BP-SUBLET R/I REAR CARPET,TRIMMING,REAR SEATS AND OTHER ATTACHMENT TO FACILIATE REPAIRS.	0742			396.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		Amount Due
					Lubrication/Fluid		
					Others		

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept		S1000005 / ICFIC1	Ms Ow Wei Kuen 262C Compassvale Street #05-133 Singapore 543262 Mobile: 91074197				
		Document No. 0					
		Document Date 21/06/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3100068925		2NRX564229	60	Raymond Seah L M	14/06/2023	14.32	--/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
9	S	BP-SUBLET TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.	0742			3168.00	
10	S	BP-SUBLET TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.	0742			2624.00	
11	1	SPC507-0D014 73 BACK SENSOR (4W0.Q. BROWN ME)	1.00	175.90		175.90	
12	2	S52159-0U919 COVER, RR BUMPER, L	1.00	429.00		429.00	
13	3	S52151-0D010 EXTENSION, RR BUMPER	1.00	243.00		243.00	
14	4	S52161-0K040 PIECE, RR BUMPER	10.00	5.30		53.00	
15	5	S58307-0D320 PANEL SUB-ASSY, BODY	1.00	588.10		588.10	
16	6	S68105-0D261 GLASS SUB-ASSY, BACK	1.00	1316.00		1316.00	
17	7	S64813-0D330 DAM, BACK WINDOW GLA	2.00	15.90		31.80	
18	8	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	2.00	108.00		216.00	
19	9	T21000-22 SIKI 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00	
20	0	S67005-0D360 PANEL SUB-ASSY, BACK	1.00	1535.20		1535.20	
21	1	S69350-0D240 LOCK ASSY, BACK DOOR - see photo	1.00	599.10		599.10	
22	2	T90975-02086 EMBLEM, SYMBOL	1.00	72.20		72.20	
23	3	S75441-0D070 PLATE, BACK DOOR NAM	1.00	68.10		68.10	
24	4	S75442-0D300 PLATE, BACK DOOR NAM	1.00	45.50		45.50	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		13,633.54		
			Labour		GST 8.00%		
			Sublet		1,090.68		
			Lubrication/Fluid		Less		
			Others		Amount Due		
			5,572.90		0.00	14,724.22	
			30.00				
			8,030.64				
			0.00				
			0.00				

Company Copy

Vehicle Diagnostic Report

2NRFE
027769 km

MHFZ28H3100068925

Borneo Motors

Printed By: Default User(1)

22/6/2023 12:59:29 pm

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
Engine and ECT	Yes	P0113	X	X	X		-	30U12100 A0202000	No
ABS/VSC/TRC							-	F15260D 120	No
EMPS							-	8965B0D 110	No
Air Conditioner							-	886500D5 7001	No
Combination Meter							-	838000U A0005	No
Rear Left Door							-	859180D0 6001	No
SRS Airbag							-	8917F0D 331	No
Immobiliser							-	-	No

Vehicle Diagnostic Report

2NRFE
027769 km

MHFZ28H3100068925

Borneo Motors

Printed By: Default User(1)

22/6/2023 1:00:08 pm

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
Engine and ECT							-	30U12100	No
								A0202000	
ABS/VSC/TRC							-	F15260D120	No
EMPS							-	8965B0D110	No
Air Conditioner							-	886500D57001	No
Combination Meter							-	838000UA0005	No
Rear Left Door							-	859180D06001	No
SRS Airbag							-	8917F0D331	No
Immobiliser							-	-	No