

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMW23006001/4Vp3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMW9250K

at Workshop m/s

Borneo 3pm

of

Insured:

SHB762D

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

\$106k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

1.8.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

706J

Vehicle: IN / OUT

Date:

Person Contacted:

L1A 43487

Veh No:

SMW9250K

Yr Regn:

17/12/20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAI

Make:

Toyota Siesta

c.c

1496

Colour

Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

27767

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MHF228H3100068925

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

10/06/23

D.O.I.

14/06/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 13k.

27/6/23 11/2 13633-54 inbound Raymond

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

1)

☐

: Final Report

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

) TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	706J
Vehicle Details	
Vehicle No.:	SMW9250K
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jun 2023
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA STANDARD (AUTO)
Primary Colour:	Brown
Manufacturing Year:	2020
Engine No.:	2NRX564229
Chassis No.:	MHFZ28H3100068925
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$17,241.00
Original Registration Date:	17 Dec 2020
First Registration Date:	17 Dec 2020
Transfer Count:	0
Actual ARF Paid:	\$17,241.00 8620
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Dec 2030
PARF Rebate Amount:	\$12,930.00
Intended COE Rebate Details	
COE Expiry Date:	16 Dec 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,714.00
COE Rebate Amount:	\$30,557.00
Total Rebate Amount:	\$43,487.00

The information contained herein is correct as at 14 Jun 2023

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)

Low Interest Rate In-House Loan by GV Cars Financing



\$0 Downpayment, Loan by GV
Cars Financing at 3.28% p.a.
Low Interest Rate
GV Automobile Centre StarAd

Lake View Credit Pte Ltd [view our cars](#)

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Sort by 20 results/page

5 vehicles



TOYOTA SIENTA

Any Category

[Advanced Search](#)[Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	TOYOTA SIENTA		Any	Any	2020	Any	Any	Any	Available
	Toyota	Sienta 1.5A X (OPC)	\$90,800	\$12,570 /yr	02-Apr-2020	1,496 cc	34,436 km	MPV	Available
Normal plate \$102,988! One retired owner, under usage 34,000km! 2x free servicing by reputable jackcars workshop! Interior/exterior/door panel are in pristine new showroom condition! Don't miss this beauty! 10years warranty! Register your interest, cal... Posted: 10-Jun-2023									
	Toyota	Sienta Hybrid 1.5A G	\$155,800	\$20,130 /yr	29-Sep-2020	1,496 cc	39,000 km	MPV	Available
Fuel Type: Petrol-Electric 1 Owner Only! Meticulously Well Maintained By Previous Owner With Very Low Mileage Done! Brand New Alike Unit! 100% Accident Free Unit! View To Believe & Appreciate It's Condition! Our Company Provide Various Loan Scheme! All Trade In Welcome! Hurry Contact Us... Hua Yang Credit Pte Ltd Posted: 10-Jun-2023									
	Toyota	Sienta 1.5A Elegance	\$114,800	\$14,610 /yr	18-Aug-2020	1,496 cc	51,600 km	MPV	Available
Buy with confidence with Toyota certified preowned selection, 145 points certification, approved service history, 5 years/100,000km mileage warranty from date of registration and complimentary servicing inclusive.1 owner. Borneo Motors (S) Posted: 09-Jun-2023									
	Toyota	Sienta Hybrid 1.5A X	\$115,800	\$14,630 /yr	08-Oct-2020	1,496 cc	34,000 km	MPV	Available
Fuel Type: Petrol-Electric 1 owner! Well maintained! Guaranteed non PHV unit. Flexible financing options available, 100% loan with \$0 driveaway available! High trade in value! Warranty for engine and gearbox! Call us for a non obligatory viewing today. SG Car Choice Pte Ltd Posted: 08-Jun-2023									
	Premium Comfort Pirelli Cinturato P7 Tyre Pirelli Cinturato P7 XL Yr 16 Made In Italy Find out more!								
	Toyota	Sienta 1.5A Standard	\$112,800	\$14,280 /yr	24-Sep-2020	1,496 cc	54,479 km	MPV	Available
Rare Sporty Black Sienta 1.5A (7-Seaters MPV) (Sliding Doors) (Rear 2nd Row Air-Con), The Perfect MPV Choice! Timely Maintained At Borneo Motors With Proof/Valid 5-Years Warranty. Genuine Low Mileage Done 54479km! Totally Like New. 1 Lady Owner. New Paintwork... Lake View Credit Pte Ltd Posted: 02-Jun-2023									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

[For old advertisements, view Expired ads](#)

20 results/page

[Compare](#)



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

*Not Authorized
her
merals
14/6/23
telephone party.*

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM <i>First H. Capital strides (smr?)</i> <i>liability check</i>	S1000020 / TPCLAIM	Ms Ow Wei Kuen 262C Compassvale Street #05-133 Singapore 543262 <i>8 days</i> <i>9/2 13633.54</i>
	Document No. 0	
	Document Date 12/06/2023	Mobile: 91074197

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MHFZ28H3100068925	2NRX564229	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:SHB 762D ACC DATE:10/06/2023 TP INS: NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM			<i>100</i>	30.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR TAILGATE AND REAR END PANEL.			<i>60</i>	120.00
3	S	BP-SUBLET TO SUPPLY AND INSTALL REAR WINDSCREEN 3M SOLAR FILM.				400.00
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
5	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.				134.64
6	B	BP-WS2 R/I REAR WINDSCREEN TO FACILIATE REPAIR.			<i>594</i>	346.50
7	B	BP-LAB2 TO TRANSFER REAR TAILGATE BOARD, WIPER MOTOR AND OTHER ATTACHMENT TO FACILIATE REPAIRS.				396.00
8	B	BP-LAB2 R/I REAR CARPET,TRIMMING,REAR SEATS AND OTHER ATTACHMENT TO FACILIATE REPAIRS.				396.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA


ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Cw Wei Kuen 262C Compassvale Street #05-133 Singapore 543262 Mobile: 91074197		
			Document No.				
			0				
			Document Date				
			12/06/2023				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MHFZ28H3100068925	2NRX564229	60	Raymond Seah L M	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. <i>792</i>			<i>3168</i>	4752.00
10	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS. <i>696 658</i>			<i>2624</i>	3936.00
11	1	SPC507-0D014 73 BACK SENSOR (4W0.Q. BROWN ME) <i>not needed</i>	1.00	175.90	<i>✓</i>	175.90
12	2	S81910-0D020 REFLECTOR ASSY, REFL <i>17</i>	1.00	77.20	<i>X</i>	77.20
13	3	S81920-0D020 REFLECTOR ASSY, REFL <i>17</i>	1.00	77.20	<i>X</i>	77.20
14	4	T81480-52070 LAMP ASSY, RR FOG, <i>17</i>	1.00	317.50	<i>X</i>	317.50
15	5	T81481-52560 BRACKET, FOG LAMP <i>17</i>	1.00	71.80	<i>X</i>	71.80
16	6	S52159-0U919 COVER, RR BUMPER, L/ <i>7.5</i>	1.00	429.00	<i>✓</i>	429.00
17	7	S52151-0D010 EXTENSION, RR BUMPER <i>RH</i>	1.00	243.00	<i>✓</i>	243.00
18	8	S52161-0D070 EXTENSION, RR BUMPER <i>R</i>	1.00	165.20	<i>X</i>	165.20
19	9	S52162-0D040 EXTENSION, RR BUMPER <i>L</i>	1.00	165.20	<i>X</i>	165.20
20	0	S52161-0K040 PIECE, RR BUMPER <i>17</i>	10.00	5.30	<i>✓</i>	53.00
21	1	S52155-0D110 SUPPORT, RR BUMPER S <i>R</i>	1.00	99.50	<i>X</i>	99.50
22	2	S52156-0D100 SUPPORT, RR BUMPER S <i>L</i>	1.00	99.50	<i>X</i>	99.50
23	3	S52575-0D280 RETAINER, RR BUMPER <i>R</i>	1.00	95.40	<i>X</i>	95.40
24	4	S52576-0D270 RETAINER, RR BUMPER <i>L</i>	1.00	95.40	<i>X</i>	95.40
25	5	S58302-0D010 PANEL SUB-ASSY, LWR <i>R</i>	1.00	944.00	<i>X</i>	944.00
26	6	S58307-0D320 PANEL SUB-ASSY, BODY <i>- end panel</i>	1.00	588.10	<i>X</i>	588.10

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less Amount Due
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Ms Ow Wei Kuen
	Document No. 0	262C Compassvale Street #05-133 Singapore 543262
	Document Date 12/06/2023	Mobile: 91074197

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3100068925		2NRX564229	60	Raymond Seah L M	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
27	7	S64716-0D170 C0 COVER, DECK TRIM, RR <i>-- garnish</i>	1.00	198.30	<i>X</i>	198.30 <i>X</i>
28	8	S58408-0D010 C0 BOARD SUB-ASSY, DECK	1.00	199.50	<i>X</i>	199.50 <i>X</i>
29	9	S68105-0D261 GLASS SUB-ASSY, BACK	1.00	1316.00	<i>1</i>	1316.00 <i>1</i>
30	0	S64813-0D330 DAM, BACK WINDOW GLA	2.00	15.90	<i>1</i>	31.80 <i>1</i>
31	1	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00	<i>1</i>	216.00 <i>1</i>
32	2	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00	<i>1</i>	200.00 <i>1</i>
33	3	S67005-0D360 PANEL SUB-ASSY, BACK	1.00	1535.20	<i>X</i>	1535.20 <i>X</i>
34	4	S67881-0D130 WEATHERSTRIP, BACK D	1.00	476.60	<i>X</i>	476.60 <i>X</i>
35	5	S69350-0D240 LOCK ASSY, BACK DOOR	1.00	599.10	<i>X</i>	599.10 <i>X</i>
36	6	T90975-02086 EMBLEM, SYMBOL	1.00	72.20	<i>1</i>	72.20 <i>1</i>
37	7	S75441-0D070 PLATE, BACK DOOR NAM	1.00	68.10	<i>1</i>	68.10 <i>1</i>
38	8	S75442-0D300 PLATE, BACK DOOR NAM	1.00	45.50	<i>1</i>	45.50 <i>1</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	19,364.34
			GST 8.00%	1,549.15
		8,655.20		
		10,309.14		
		400.00		
		0.00	Less	0.00
		0.00	Amount Due	20,913.49

Please acknowledge receipt of vehicle
Signature:
Date:

Parts
Labour
Sublet
Lubrication/Fluid
Others

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TP/DS Final

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		Ms Ow Wei Kuen 262C Compassvale Street #05-133 Singapore 543262 Mobile: 91074197		
			Document No.				
			0				
			Document Date				
			21/06/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3100068925		2NRX564229	60	Raymond Seah L M	14/06/2023 14.32 --/--/----		0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:SHB 762D ACC DATE:10/06/2023 TP INS:FIRST CAPITAL NO OF REPAIR DAYS:08 DATE-IN:14/06/2023 DATE SURVEY:14/06/2023 BY:LKK-MARCUS AUTHORISED ON: -TP/DS CLAIM				30.00	
2	S	BP-SUBLET TO SUPPLY AND INSTALL REAR WINDSCREEN 3M SOLAR FILM.	0650			400.00	
3	S	BP-SUBLET SUPPLY SEALANT (NETT) FOR REAR TAILGATE AND REAR END PANEL.	0742			120.00	
4	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			198.00	
5	S	BP-SUBLET TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.	0742			134.64	
6	S	BP-SUBLET R/I REAR WINDSCREEN TO FACILIATE REPAIR.	0742			594.00	
7	S	BP-SUBLET TO TRANSFER REAR TAILGATE BOARD, WIPER MOTOR AND OTHER ATTACHMENT TO FACILIATE REPAIRS.	0742			396.00	
8	S	BP-SUBLET R/I REAR CARPET,TRIMMING,REAR SEATS AND OTHER ATTACHMENT TO FACILIATE REPAIRS.	0742			396.00	
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd							
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		Amount Due
					Lubrication/Fluid		
					Others		

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

17 UBI ROAD 4

SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept		S1000005 / ICFIC1	Ms Ow Wei Kuen 262C Compassvale Street #05-133 Singapore 543262 Mobile: 91074197				
		Document No. 0					
		Document Date 21/06/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3100068925		2NRX564229	60	Raymond Seah L M	14/06/2023 14.32		--/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
9	S	BP-SUBLET TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.	0742			3168.00	
10	S	BP-SUBLET TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.	0742			2624.00	
11	1	SPC507-0D014 73 BACK SENSOR (4W0.Q. BROWN ME)	1.00	175.90		175.90	
12	2	S52159-0U919 COVER, RR BUMPER, L	1.00	429.00		429.00	
13	3	S52151-0D010 EXTENSION, RR BUMPER	1.00	243.00		243.00	
14	4	S52161-0K040 PIECE, RR BUMPER	10.00	5.30		53.00	
15	5	S58307-0D320 PANEL SUB-ASSY, BODY	1.00	588.10		588.10	
16	6	S68105-0D261 GLASS SUB-ASSY, BACK	1.00	1316.00		1316.00	
17	7	S64813-0D330 DAM, BACK WINDOW GLA	2.00	15.90		31.80	
18	8	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00		216.00	
19	9	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00	
20	0	S67005-0D360 PANEL SUB-ASSY, BACK	1.00	1535.20		1535.20	
21	1	S69350-0D240 LOCK ASSY, BACK DOOR - see plates	1.00	599.10		599.10	
22	2	T90975-02086 EMBLEM, SYMBOL	1.00	72.20		72.20	
23	3	S75441-0D070 PLATE, BACK DOOR NAM	1.00	68.10		68.10	
24	4	S75442-0D300 PLATE, BACK DOOR NAM	1.00	45.50		45.50	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle			13,633.54		
			Parts		5,572.90		
			Labour		30.00		
			Sublet		8,030.64		
			Lubrication/Fluid		0.00		
		Others		0.00			
				GST 8.00%			
				Less			
				Amount Due			
				14,724.22			

Company Copy

Vehicle Diagnostic Report

2NRFE
027769 km

MHFZ28H3100068925

Borneo Motors

Printed By: Default User(1)

22/6/2023 12:59:29 pm

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
Engine and ECT	Yes	P0113	X	X	X		-	30U12100 A0202000	No
ABS/VSC/TRC							-	F15260D 120	No
EMPS							-	8965B0D 110	No
Air Conditioner							-	886500D5 7001	No
Combination Meter							-	838000U A0005	No
Rear Left Door							-	859180D0 6001	No
SRS Airbag							-	8917F0D 331	No
Immobiliser							-	-	No

Vehicle Diagnostic Report

2NRFE
027769 km

MHFZ28H3100068925

Borneo Motors

Printed By: Default User(1)

22/6/2023 1:00:08 pm

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information							RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed				
Engine and ECT									30U12100 A0202000	No
ABS/VSC/TRC									F15260D 120	No
EMPS									8965B0D 110	No
Air Conditioner									886500D5 7001	No
Combination Meter									838000U A0005	No
Rear Left Door									859180D0 6001	No
SRS Airbag									8917F0D 331	No
Immobiliser									-	No



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
62 West Coast Ferry Road
Singapore 126978, Fax: 6631 1579



TOYOTA

For REF:

INTERNAL INVOICE

Account Details	Account No.	Customer Details
New vehicle preparation PDI ***** For use by BMS PDI *****	i0100001 / NEWVEHIC	Ms WK Ow
	Document No. 52215013	262C Compassvale Street #05-133 Singapore 543262
	Document Date 25/12/2020	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4		SMW9250K	1	43979	DL-0028

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MHFZ28H3100068925	2NRX564229	00	Ng Wan Nee	11/12/2020 0.00	16/12/2020 12.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	S	D781D COMPLIMENTARY SOLAR FILM - CLASSIC FILM 3M (ALL PD1085) Retail Classic Solar Film	0741	1.00	538.00	538.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary		Total	538.00
	Please acknowledge receipt of vehicle	Parts	0.00	GST 0.00%	0.00
		Labour	0.00		
		Sublet	538.00	Less	0.00
		Lubrication/Fluid	0.00		
		Others	0.00	Amount Due	538.00

Company Copy