

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMW23006001/4VP3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMW9250Kat Workshop m/s Borneo 3pm

of _____

Insured: SHB762D

Policy No. _____


Claims No. TAX/06/23/2024

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**Bal. or Market Value: 8106k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or NoLum Sum: 1.8.1 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 706JDate: _____ Person Contacted: LIA 43487 Vehicle: IN / OUTVeh No: SMW9250K Yr Regn: 17/12/20Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: Toyota Siesta c.c. 1496Colour: Brown A/C: Insured / Std / NI / NASp. Reading: 27767 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MHF228H3100068925Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 185/60R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 10/06/23 D.O.I. 14/06/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Dep 13k.27/6/23 11/2 13633.54 informed Raymond (red 5978.30, 30%)

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 8

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) 27/6/23-typistAdd Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

TOTAL

Report Format: TPLump Sum / I.B.I. (\$ 13,633.54)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	706J
Vehicle Details	
Vehicle No.:	SMW9250K
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jun 2023
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA STANDARD (AUTO)
Primary Colour:	Brown
Manufacturing Year:	2020
Engine No.:	2NRX564229
Chassis No.:	MHFZ28H3100068925
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$17,241.00
Original Registration Date:	17 Dec 2020
First Registration Date:	17 Dec 2020
Transfer Count:	0
Actual ARF Paid:	\$17,241.00 <i>8620</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Dec 2030
PARF Rebate Amount:	\$12,930.00
Intended COE Rebate Details	
COE Expiry Date:	16 Dec 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$40,714.00
COE Rebate Amount:	\$30,557.00
Total Rebate Amount:	\$43,487.00

The information contained herein is correct as at 14 Jun 2023

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Low Interest Rate In-House Loan by GV Cars Financing



\$0 Downpayment, Loan by GV
Cars Financing at 3.28% p.a.
Low Interest Rate
GV Automobile Centre StarAd

Lake View Credit Pte Ltd view our cars

- > Low prices guaranteed
- > Specialist in Japanese cars
- > Easy loan approval
- > All terms are negotiable

Sort by 20 results/page

5 vehicles



TOYOTA SIENTA

Any Category

Advanced Search



Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	TOYOTA SIENTA		Any	Any	2020	Any	Any	Any	Available
	Toyota	Sienta 1.5A X (OPC)	\$90,800	\$12,570 /yr	02-Apr-2020	1,496 cc	34,436 km	MPV	Available
Normal plate \$102,988! One retired owner, under usage 34,000km! 2x free servicing by reputable jackcars workshop! Interior/exterior/door panel are in pristine new showroom condition! Don't miss this beauty! 10years warranty! Register your interest, cal... PREMIUM AD									
Posted: 10-Jun-2023									
	Toyota	Sienta Hybrid 1.5A G	\$155,800	\$20,130 /yr	29-Sep-2020	1,496 cc	39,000 km	MPV	Available
Fuel Type: Petrol-Electric 1 Owner Only! Meticulously Well Maintained By Previous Owner With Very Low Mileage Done! Brand New Alike Unit! 100% Accident Free Unit! View To Believe & Appreciate It's Condition! Our Company Provide Various Loan Scheme! All Trade In Welcome! Hurry Contact Us... PREMIUM AD									
Hua Yang Credit Pte Ltd Posted: 10-Jun-2023									
	Toyota	Sienta 1.5A Elegance	\$114,800	\$14,610 /yr	18-Aug-2020	1,496 cc	51,600 km	MPV	Available
Buy with confidence with Toyota certified preowned selection, 145 points certification, approved service history, 5 years/100,000km mileage warranty from date of registration and complimentary servicing inclusive.1 owner. PREMIUM AD									
Borneo Motors (S) Posted: 09-Jun-2023									
	Toyota	Sienta Hybrid 1.5A X	\$115,800	\$14,630 /yr	08-Oct-2020	1,496 cc	34,000 km	MPV	Available
Fuel Type: Petrol-Electric 1 owner! Well maintained! Guaranteed non PHV unit. Flexible financing options available, 100% loan with \$0 driveaway available! High trade in value! Warranty for engine and gearbox! Call us for a non obligatory viewing today. PREMIUM AD									
SG Car Choice Pte Ltd Posted: 08-Jun-2023									
	Premium Comfort Pirelli Cinturato P7 Tyre Pirelli Cinturato P7 XL Yr 16 Made In Italy Find out more!								
	Toyota	Sienta 1.5A Standard	\$112,800	\$14,280 /yr	24-Sep-2020	1,496 cc	54,479 km	MPV	Available
Rare Sporty Black Sienta 1.5A (7-Seaters MPV) (Sliding Doors) (Rear 2nd Row Air-Con), The Perfect MPV Choice! Timely Maintained At Borneo Motors With Proof/Valid 5-Years Warranty, Genuine Low Mileage Done 54479km! Totally Like New. 1 Lady Owner. New Paintwork... PREMIUM AD									
Lake View Credit Pte Ltd Posted: 02-Jun-2023									

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

20 results/page

Compare



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

*Not Authorized
her
wera's
14/6/23
telephone party.*

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM <i>First Hl Capitol strides (smr?)</i>	S1000020 / TPCLAIM	Ms Cw Wei Kuen 262C Compassvale Street #05-133 Singapore 543262 Mobile: 91074197
<i>liability check</i>	Document No. 0	<i>8 days</i> <i>9/2 813633.54</i>
	Document Date 12/06/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MHFZ28H3100068925	2NRX564229	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:SHB 762D ACC DATE:10/06/2023 TP INS: NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM			<i>100</i>	30.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR TAILGATE AND REAR END PANEL.			<i>60</i>	120.00 ✓
3	S	BP-SUBLET TO SUPPLY AND INSTALL REAR WINDSCREEN 3M SOLAR FILM.				400.00 ✓
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00 ✓
5	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.				134.64 ✓
6	B	BP-WS2 R/I REAR WINDSCREEN TO FACILIATE REPAIR.			<i>594</i>	346.50 ✓
7	B	BP-LAB2 TO TRANSFER REAR TAILGATE BOARD, WIPER MOTOR AND OTHER ATTACHMENT TO FACILIATE REPAIRS.				396.00 ✓
8	B	BP-LAB2 R/I REAR CARPET,TRIMMING,REAR SEATS AND OTHER ATTACHMENT TO FACILIATE REPAIRS.				396.00 ✓

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Ms Ow Wei Kuen
	Document No. 0	262C Compassvale Street #05-133 Singapore 543262
	Document Date 12/06/2023	Mobile: 91074197

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3100068925		2NRX564229	60	Raymond Seah L M	--/--/----	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. 792			3168	4752.00
10	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS. 626 658			2624	3936.00
11	1	SPC507-0D014 73 BACK SENSOR (4W0.Q. BROWN ME)	1.00	175.90		175.90
12	2	S81910-0D020 REFLECTOR ASSY, REFL R	1.00	77.20	X	77.20
13	3	S81920-0D020 REFLECTOR ASSY, REFL L	1.00	77.20	X	77.20
14	4	T81480-52070 LAMP ASSY, RR FOG,	1.00	317.50	X	317.50
15	5	T81481-52560 BRACKET, FOG LAMP	1.00	71.80	X	71.80
16	6	S52159-0U919 COVER, RR BUMPER, L/	1.00	429.00		429.00
17	7	S52151-0D010 EXTENSION, RR BUMPER RH	1.00	243.00		243.00
18	8	S52161-0D070 EXTENSION, RR BUMPER R	1.00	165.20	X	165.20
19	9	S52162-0D040 EXTENSION, RR BUMPER L	1.00	165.20	X	165.20
20	0	S52161-0K040 PIECE, RR BUMPER	10.00	5.30		53.00
21	1	S52155-0D110 SUPPORT, RR BUMPER S R	1.00	99.50	X	99.50
22	2	S52156-0D100 SUPPORT, RR BUMPER S L	1.00	99.50	X	99.50
23	3	S52575-0D280 RETAINER, RR BUMPER R	1.00	95.40	X	95.40
24	4	S52576-0D270 RETAINER, RR BUMPER L	1.00	95.40	X	95.40
25	5	S58302-0D010 PANEL SUB-ASSY, LWR R	1.00	944.00	X	944.00
26	6	S58307-0D320 PANEL SUB-ASSY, BODY - end panel body	1.00	588.10	X	588.10

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Ms Ow Wei Kuen
	Document No. 0	262C Compassvale Street #05-133 Singapore 543262
	Document Date 12/06/2023	Mobile: 91074197

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MHFZ28H3100068925	2NRX564229	60	Raymond Seah L M	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
27	7	S64716-0D170 C0 COVER, DECK TRIM, RR <i>gumish</i>	1.00	198.30	X	198.30 X
28	8	S58408-0D010 C0 BOARD SUB-ASSY, DECK	1.00	199.50	X	199.50 X
29	9	S68105-0D261 GLASS SUB-ASSY, BACK	1.00	1316.00	X	1316.00 X
30	0	S64813-0D330 DAM, BACK WINDOW GLA	2.00	15.90	X	31.80 X
31	1	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00	X	216.00 X
32	2	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00	X	200.00 X
33	3	S67005-0D360 PANEL SUB-ASSY, BACK	1.00	1535.20	X	1535.20 X
34	4	S67881-0D130 WEATHERSTRIP, BACK D	1.00	476.60	X	476.60 X
35	5	S69350-0D240 LOCK ASSY, BACK DOOR	1.00	599.10	X	599.10 X
36	6	T90975-02086 EMBLEM, SYMBOL	1.00	72.20	X	72.20 X
37	7	S75441-0D070 PLATE, BACK DOOR NAM	1.00	68.10	X	68.10 X
38	8	S75442-0D300 PLATE, BACK DOOR NAM	1.00	45.50	X	45.50 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudices" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed as it is subject to the approval of the Insurance Company

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total	19,364.34
Ack: Please acknowledge receipt of vehicle.	Signature:	Parts 8,655.20	GST 8.00%	1,549.15
Date:	Signature:	Labour 10,309.14		
	Signature:	Sublet 400.00		
	Signature:	Lubrication/Fluid 0.00	Less	0.00
	Signature:	Others 0.00	Amount Due	20,913.49

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TP/DS Finalize

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept			S1000005 / ICFIC1		Ms Ow Wei Kuen 262C Compassvale Street #05-133 Singapore 543262 Mobile: 91074197		
			Document No.				
			0				
			Document Date				
			21/06/2023				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3100068925		2NRX564229	60	Raymond Seah L M	14/06/2023 14.32 --/--/----		0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:SHB 762D ACC DATE:10/06/2023 TP INS:FIRST CAPITAL NO OF REPAIR DAYS:08 DATE-IN:14/06/2023 DATE SURVEY:14/06/2023 BY:LKK-MARCUS AUTHORISED ON: -TP/DS CLAIM				30.00	
2	S	BP-SUBLET TO SUPPLY AND INSTALL REAR WINDSCREEN 3M SOLAR FILM.	0650			400.00	
3	S	BP-SUBLET SUPPLY SEALANT (NETT) FOR REAR TAILGATE AND REAR END PANEL.	0742			120.00	
4	S	BP-SUBLET TO RESET ECU AND REPROGRAMME	0742			198.00	
5	S	BP-SUBLET TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.	0742			134.64	
6	S	BP-SUBLET R/I REAR WINDSCREEN TO FACILIATE REPAIR.	0742			594.00	
7	S	BP-SUBLET TO TRANSFER REAR TAILGATE BOARD, WIPER MOTOR AND OTHER ATTACHMENT TO FACILIATE REPAIRS.	0742			396.00	
8	S	BP-SUBLET R/I REAR CARPET,TRIMMING,REAR SEATS AND OTHER ATTACHMENT TO FACILIATE REPAIRS.	0742			396.00	
For & on behalf of			Customer's Signature		Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Company Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
MS First Capital Insurance Ltd 16 Raffles Quay #42-01 Hong Leong Building Singapore 048581 Attn: Motor Claims Dept		S1000005 / ICFIC1	Ms Ow Wei Kuen				
		Document No. 0	262C Compassvale Street #05-133 Singapore 543262				
		Document Date 21/06/2023	Mobile: 91074197				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MHFZ28H3100068925		2NRX564229	60	Raymond Seah L M	14/06/2023 14.32		--/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
9	S	BP-SUBLET TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.	0742			3168.00	
10	S	BP-SUBLET TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.	0742			2624.00	
11	1	SPC507-0D014 73 BACK SENSOR (4W0.Q. BROWN ME)	1.00	175.90		175.90	
12	2	S52159-0U919 COVER, RR BUMPER, L	1.00	429.00		429.00	
13	3	S52151-0D010 EXTENSION, RR BUMPER	1.00	243.00		243.00	
14	4	S52161-0K040 PIECE, RR BUMPER	10.00	5.30		53.00	
15	5	S58307-0D320 PANEL SUB-ASSY, BODY	1.00	588.10		588.10	
16	6	S68105-0D261 GLASS SUB-ASSY, BACK	1.00	1316.00		1316.00	
17	7	S64813-0D330 DAM, BACK WINDOW GLA	2.00	15.90		31.80	
18	8	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	2.00	108.00		216.00	
19	9	T21000-22 SIKI 207. G+P ADHESIVE PRIMER	1.00	200.00		200.00	
20	0	S67005-0D360 PANEL SUB-ASSY, BACK	1.00	1535.20		1535.20	
21	1	S69350-0D240 LOCK ASSY, BACK DOOR - see plates	1.00	599.10		599.10	
22	2	T90975-02086 EMBLEM, SYMBOL	1.00	72.20		72.20	
23	3	S75441-0D070 PLATE, BACK DOOR NAM	1.00	68.10		68.10	
24	4	S75442-0D300 PLATE, BACK DOOR NAM	1.00	45.50		45.50	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle			13,633.54		
					GST 8.00%		
					1,090.68		
					Less		
					Amount Due		
		Parts	5,572.90				
		Labour	30.00				
		Sublet	8,030.64				
		Lubrication/Fluid	0.00				
		Others	0.00				
				14,724.22			

Company Copy

Vehicle Diagnostic Report

2NRFE
027769 km

MHFZ28H3100068925

Borneo Motors

Printed By: Default User(1)

22/6/2023 12:59:29 pm

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed			
Engine and ECT	Yes	P0113	X	X	X		-	30U12100 A0202000	No
ABS/VSC/TRC							-	F15260D 120	No
EMPS							-	8965B0D 110	No
Air Conditioner							-	886500D5 7001	No
Combination Meter							-	838000U A0005	No
Rear Left Door							-	859180D0 6001	No
SRS Airbag							-	8917F0D 331	No
Immobiliser							-	-	No

Vehicle Diagnostic Report

2NRFE
027769 km

MHFZ28H3100068925

Borneo Motors

Printed By: Default User(1)

22/6/2023 1:00:08 pm

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information							RoB	Calibration	Configure
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed				
Engine and ECT									30U12100 A0202000	No
ABS/VSC/TRC									F15260D 120	No
EMPS									8965B0D 110	No
Air Conditioner									886500D5 7001	No
Combination Meter									838000U A0005	No
Rear Left Door									859180D0 6001	No
SRS Airbag									8917F0D 331	No
Immobiliser									-	No



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
62 West Coast Ferry Road
Singapore 126978, Fax: 6631 1579



TOYOTA

For REF:

INTERNAL INVOICE

Account Details	Account No.	Customer Details
New vehicle preparation PDI ***** For use by BMS PDI *****	i0100001 / NEWVEHIC	Ms WK Ow
	Document No. 52215013	262C Compassvale Street #05-133 Singapore 543262
	Document Date 25/12/2020	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4		SMW9250K	1	43979	DL-0028
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MHFZ28H3100068925	2NRX564229	00	Ng Wan Nee	11/12/2020 0.00	16/12/2020 12.00		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	S	D781D COMPLIMENTARY SOLAR FILM - CLASSIC FILM 3M (ALL PD1085) Retail Classic Solar Film	0741	1.00	538.00	538.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			538.00
	Please acknowledge receipt of vehicle	Parts 0.00	GST 0.00% 0.00
		Labour 0.00	Less 0.00
		Sublet 538.00	
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 538.00

Company Copy