



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

TP/DS

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM <i>liability check</i>			S1000020 / TPCLAIM		Ms Ow Wei Kuen		
			Document No.		[REDACTED]		
			0		[REDACTED]		
			Document Date		[REDACTED]		
12/06/2023							

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MHFZ28H3100068925	2NRX564229	60	Raymond Seah L M	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY-AI SUNDRIES TP VEH:SHB 762D ACC DATE:10/06/2023 TP INS: NO OF REPAIR DAYS: DATE-IN: DATE SURVEY: BY: AUTHORISED ON: -TP/DS CLAIM				30.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR TAILGATE AND REAR END PANEL.				120.00
3	S	BP-SUBLET TO SUPPLY AND INSTALL REAR WINDSCREEN 3M SOLAR FILM.				400.00
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00
5	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.				134.64
6	B	BP-WS2 R/I REAR WINDSCREEN TO FACILIATE REPAIR.				346.50
7	B	BP-LAB2 TO TRANSFER REAR TAILGATE BOARD, WIPER MOTOR AND OTHER ATTACHMENT TO FACILIATE REPAIRS.				396.00
8	B	BP-LAB2 R/I REAR CARPET,TRIMMING,REAR SEATS AND OTHER ATTACHMENT TO FACILIATE REPAIRS.				396.00

For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature	Charge Summary	Total
		Please acknowledge receipt of vehicle	Parts	Less
			Labour	
			Sublet	Amount Due
			Lubrication/Fluid	
			Others	

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Ms Ow Wei Kuen
	Document No. 0	
	Document Date 12/06/2023	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MHFZ28H3100068925	2NRX564229	60	Raymond Seah L M	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				4752.00
10	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.				3936.00
11	1	SPC507-0D014 73 BACK SENSOR (4W0.Q. BROWN ME)	1.00	175.90		175.90
12	2	S81910-0D020 REFLECTOR ASSY, REFL	1.00	77.20		77.20
13	3	S81920-0D020 REFLECTOR ASSY, REFL	1.00	77.20		77.20
14	4	T81480-52070 LAMP ASSY, RR FOG,	1.00	317.50		317.50
15	5	T81481-52560 BRACKET, FOG LAMP	1.00	71.80		71.80
16	6	S52159-0U919 COVER, RR BUMPER, L/	1.00	429.00		429.00
17	7	S52151-0D010 EXTENSION, RR BUMPER	1.00	243.00		243.00
18	8	S52161-0D070 EXTENSION, RR BUMPER	1.00	165.20		165.20
19	9	S52162-0D040 EXTENSION, RR BUMPER	1.00	165.20		165.20
20	0	S52161-0K040 PIECE, RR BUMPER	10.00	5.30		53.00
21	1	S52155-0D110 SUPPORT, RR BUMPER S	1.00	99.50		99.50
22	2	S52156-0D100 SUPPORT, RR BUMPER S	1.00	99.50		99.50
23	3	S52575-0D280 RETAINER, RR BUMPER	1.00	95.40		95.40
24	4	S52576-0D270 RETAINER, RR BUMPER	1.00	95.40		95.40
25	5	S58302-0D010 PANEL SUB-ASSY, LWR	1.00	944.00		944.00
26	6	S58307-0D320 PANEL SUB-ASSY, BODY	1.00	588.10		588.10

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors


Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Ow Wei Kuen [REDACTED] [REDACTED]			
			Document No. 0					
			Document Date 12/06/2023					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	NSP170R	MWYNKT S4	17/12/2020	SMW9250K	0	22576	69DSSMW9250K	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MHFZ28H3100068925		2NRX564229	60	Raymond Seah L M	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
27	7	S64716-0D170 C0 COVER, DECK TRIM, RR			1.00	198.30		198.30
28	8	S58408-0D010 C0 BOARD SUB-ASSY, DECK			1.00	199.50		199.50
29	9	S68105-0D261 GLASS SUB-ASSY, BACK			1.00	1316.00		1316.00
30	0	S64813-0D330 DAM, BACK WINDOW GLA			2.00	15.90		31.80
31	1	T21000-20 SIKI 182010 SIKI TACK GO! (BLA			2.00	108.00		216.00
32	2	T21000-22 SIKI 207. G+P ADHESIVE PRIMER			1.00	200.00		200.00
33	3	S67005-0D360 PANEL SUB-ASSY, BACK			1.00	1535.20		1535.20
34	4	S67881-0D130 WEATHERSTRIP, BACK D			1.00	476.60		476.60
35	5	S69350-0D240 LOCK ASSY, BACK DOOR			1.00	599.10		599.10
36	6	T90975-02086 EMBLEM, SYMBOL			1.00	72.20		72.20
37	7	S75441-0D070 PLATE, BACK DOOR NAM			1.00	68.10		68.10
38	8	S75442-0D300 PLATE, BACK DOOR NAM			1.00	45.50		45.50
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts		19,364.34		
				Labour		1,549.15		
		Sublet						
		Lubrication/Fluid		Less				
		Others		0.00				
				Amount Due		20,913.49		

Customer Copy