Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.

79 Robinson Road #09-01 Singapore 068897

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: JANICE KOH Date: 16 Jun 2023

Preliminary Advice

Vehicle No : TRD1175M Accident Date : 24/04/2023

Make : TRAILER SIN TRANS ENGINEERING PTE Policy No. : SPMF100000019

LTD

Assignment Date : 23/05/2023 Excess : S\$0.00 Date of Inspection : 25/05/2023 Est. Duration of Repair : 14

: ASM AUTOMOTIVE SERVICES PTE LTD (HQ) Inspection At

NO.13 PIONEER SECTOR 1

SINGAPORE 628424

Point of Impact / General Description of Damages

Pending for investigation.

Repairer's Estimate (Gross)	:S\$	30,897.20
Revised Amount	:S\$	27,322.40
Check Items (Estimated)	:S\$	1,530.80
Total	:S\$	28,853.20

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	N.A
COE / PARF Rebate	:S\$	0.00
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(X	()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :